



Dear Editor,

The wiper valve, P/N 7547068, (Item 16 of Fig 280 in TM 9-2320-273-24P, and Item 43 of Fig 139 in TM 9-2320-283-24P), for the M915-M920 is no longer available. You'll have to replace the entire wiper system. NSN 2540-01-312-4718 gets a motor kit with all the parts necessary. After the kit is installed, a new wiper valve, NSN 4820-00-753-9695, can then be used. This valve will only work with the new wiper motor.

CW3 Wilson J. Quebedeaux
LAARNG

Editor's Note:

Good looking out, Mr. Quebedeaux. According to TACOM, reservoir kit, NSN 2540-01-312-4719, and wiper arms kit, NSN 2540-01-390-2717, will complete the upgrade of the wiper system.