



REMEMBER TO DO  
YOUR PM OR YOU MAY  
BE LEFT OUT TO SEA!

## Cab Cracks Make M939 NMC

TACOM GPM 06-005 gave inspection criteria for stress cracks in the cab structure of armored M939-series 5-ton trucks in paragraph 3-B. These inspections no longer apply because now any crack makes your M939 NMC. See TACOM GPM 06-009 for more guidance on cab cracking:

<https://aeps2.ria.army.mil/commodity/pubs/tacom/bulletin/cab-crack-repair-2.pdf>

## DOD Maintenance Awards

Red River Army Depot won the 2006 DOD Maintenance Award for its HMMWV RECAP work. The 297th Trans Co., Ft Hood, TX, won in the medium-sized unit category. At the Army depot level, winners of Shingo Prizes for Excellence in Manufacturing were Rock Island Arsenal—gold prize for its Forward Repair System; Letterkenny AD and Red River AD—silver prize for the HMMWV; and Tobyhanna AD—bronze prize for the AN/TPS-75 radar system.

## FMTV Tire Chain Update

Tire chain assembly, NSN 2540-00-933-9033, is no longer authorized for your FMTVs, so don't use these chains. Use NSN 2540-01-483-2930 or NSN 2540-01-492-2989 instead. Remember, once the chains are installed, CTIS must be in highway mode. And don't exceed the maximum speed limits of 10 mph on highway and 15 mph off highway.

## HMMWV ENGINE OIL PRESSURE CHANGES

The current engine oil pressure requirements in all HMMWV national maintenance work requirements (NMWRs) and technical manuals have been revised. Operating oil pressure requirements for engine rpm above idle should be changed from 40-50 psi to 30-50 psi and 40 psi should be changed to 30 psi. Minimum oil pressure at idle will remain 10 psi. Make a note until updates are made.

## HMMWV TIRE CHAIN

NSN 2540-01-530-6341 gets an improved tire chain for the HMMWV. This new "alloy all-square pattern" chain is made by PEWAG. It's easier to install or dismount, gives a smoother ride, has a self-tensioner, and lasts longer than the present twist-lock, ladder-style chain.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life <sup>right now</sup> on  
the Condition of Your Equipment?