


Free Kit for Tractor Truck ABS



Fleet users, there's a free kit available to power the pin in the inter-vehicular cable receptacle on certain M915A2, M915A3, M915A4, M916A1, and M916A2 tractors. This allows the vehicle ABS system to communicate with the trailer ABS.

The kit provides continuous power to Pin 7 at the seven-way 12-volt trailer receptacle located on the tractor. Note that only trucks with the following serial numbers are affected by this kit:

- **M915A2:** All serial numbers
- **M915A3:** 902163-902167, F70198-F70204, F83323, H76647-H77198
- **M915A4:** B10592-B10596, F57501-F57595, F57616-F57636, F82596, F82662-F82683, F82689-F82695, F82697-F82716, G70505, G79031, H43165-H43194, H58823-H58832, H58838-H58907, H58913-H58932, H66557-H66571, H72548-H72584, J51638, J53164-J53183, J56570-J56627, J56194, J98083-J98103, J98462-J98645, K01115-K01171, K51069-K51126, K67267-K67270, K70237-K70267
- **M916A1/A2:** All serial numbers

To get the kit, contact TACOM at DSN 786-6557, (586) 574-6557, or e-mail:

[@us.army.mil](mailto:us.army.mil)

Or contact TACOM at DSN 786-6168, (586) 574-6168, or e-mail:

[@us.army.mil](mailto:us.army.mil)