

M198
Howitzers...

CHANGE STENCIL ON CARRYING CASE

ALL ACTIVE AND NATIONAL GUARD HOWITZER UNITS SHOULD HAVE HAD THEIR M198 BREECHES MODIFIED BY NOW SO THEY CAN FIRE M232 MACS ZONE 5 PROPELLING CHARGES.

THE MODIFICATION BROUGHT A NEW FIRING MECHANISM BLOCK ASSEMBLY AND A NEW FIRING MECHANISM.

AS A RESULT, THE LETTERING ON THE FIRING MECHANISM'S CARRYING CASE NEEDS TO BE CHANGED TO READ...

**FIRING MECH BLOCK
ASSEMBLY-11581434
FIRING MECHANISM
ASSEMBLY (M49)-11580122
2-FIRING PIN-11578911**

YOU CAN USE BLACK PAINT AND STENCILS TO MAKE THESE CHANGES OR HAND-LETTER THEM WITH A PERMANENT MARKER AFTER PAINTING OUT THE OLD LETTERING.