

M939-Series  
Trucks...

# THE REAL DEAL FOR AXLE SEALS

I KEEP ORDERING  
A SEAL ASSEMBLY  
FOR MY M939 AND  
I KEEP GETTING THE  
**WRONG SEAL!**

SOLDIER,  
YOUR TM  
NEEDS TO BE  
**UPDATED!**

Dear Half-Mast,

We had an M939-series 5-ton truck with a bad front inner axle seal. I ordered the seal assembly shown as Item 28 in Figure 236 of TM 9-2320-272-24P, but that brought the wrong seal. When that happened, I ordered just the seal shown as Item 30, but that brought the wrong part, too! How do I get the seal I need?

SPC J.D.

Dear Specialist J.D.,

You're not the first soldier that this has happened to. The TM needs to be updated with the right information:

Use NSN 5330-01-271-9362 to get the seal used on M939A2s with the original Carden CV joints. Seal assembly, NSN 5330-01-271-9490, includes this seal. And use NSN 5330-00-145-8355 to get the seal for the newer, rubber-encased CV joints found on all basic, -A1, and -A2 model M939s. You'll need NSN 4320-00-734-6951 to get the seal assembly for these trucks.

*Half-Mast*