


HYDRAULIC SYSTEM SOLENOIDS



Failed solenoids are becoming all too common with the IHMEE's hydraulic system. Problem is, you'll scratch your head trying to find replacement solenoids for the excavator.

The manufacturer has some changes in the works. Make a note of these changes in Figs 163 and 173 in TM 5-2420-230-24P until there's a change or revision to the technical manual.



Item	Fig #	Function	PN	NSN 4810-01-
11	163	FEL lift	157B4033	No NSN
11	163	FEL 4 in 1	157B4033	No NSN
18	163	FEL float	157B4216	456-1802
29	163	FEL lift	157B4616	No NSN
19	173	B/hoe boom	157B4033	No NSN
42	173	B/hoe dipper	157B4716	No NSN
21	173	B/hoe stabilizer	157B4217	539-9405
19	173	B/hoe swing	157B4033	No NSN
19	173	B/hoe bucket	157B4033	No NSN
32	173	B/hoe auxiliary	157B4616	No NSN

You can order new solenoids without NSNs directly from Oshkosh Truck Corp. by calling (800) 392-9921, ext. 2259.