

Connie's POST SCRIPTS

M1022 Dolly Set Data Plate

Use NSN 7690-01-268-4743 to get the parking brake data plate for the M1022 dolly set. This NSN fills in the parts info missing from Item 10, Fig 27 of TM 9-2330-379-14&P.

HEMTT Blower Motor Assembly

The wrong mounting adapter plate was packaged with the HEMTT's heater blower motor assembly, NSN 2910-01-422-7758. The assembly is shown as Item 16 in Fig 400 of TM 9-2320-279-24P. Order the right plate with NSN 4140-01-531-1545.

Idler Pulley for HMMWVs

Use NSN 3020-01-482-1834 to get the grooved idler pulley for the M1123, M1025A2, M1035A2, M1043A2, M1045A2, and M1097A2 HMMWVs. This NSN replaces the one shown as Item 4 in Fig 33-A1 in C1 of TM 9-2320-280-24P-1.

Better Bracket for CMSE

The M1097A1 version of the contact maintenance shop equipment has an alternator bracket for the under-hood welder that's not strong enough to do its job. The bracket lets the alternator move too much, which results in loss of power to the welder, bolts breaking, and belts slipping off the pulleys. To get a bracket attachment to prevent the bracket from moving and instructions on how to install it, contact TACOM-Rock Island's at DSN 793-4750/(309) 782-4750 or email @ria.army.mil

Antifreeze NSNs

The antifreeze NSNs shown in operator TM expendable supply lists for most vehicles shows up on FED LOG as terminal items. Order NSN 6850-01-464-9125 for a 1-gal container. Use NSN 6850-01-464-9137 to get a 5-gal container of antifreeze.

LIGHTWEIGHT MAINTENANCE ENCLOSURE

If you're ready to scrap your old frame-type, medium maintenance tent, NSN 8340-00-951-6419, you need to get its replacement: the Type I lightweight maintenance enclosure (LME). It's available in green, NSN 8340-01-456-3637, and tan, NSN 8340-01-507-4375. The LME is modular and extendable, with room for wheeled and tracked vehicles. It comes equipped with its own standard 70-amp power distribution box and standard fluorescent light set.

New NSN for M872A3 Brake Shoe Assembly

The pin-type anchor system used on the brakes in your M872A3 flatbed trailers is history. An approved SMART suggestion changed the brakes to a free-floating brake system, and solves the problem of pivot pin rusting and brake shoe seizing. Order the new brake shoe kit with NSN 2530-01-540-7667. You'll get a pair of brake shoes and the hardware to do a brake job on one wheel. That kit replaces Items 1 through 10 in Fig 15 of TM 9-2330-359-14&P.

M1 TANKS REQUIRE UPDATED GUN CARD

Your M1-series tank is officially **Not Fully Mission Capable** if you don't accurately update the DA Form 2408-4, *Weapon Record Data Card*, after firing, borescoping or exercising the main gun. The gun card should also be updated whenever the tank has been fielded, overhauled, rebuilt, turned in, or transferred to another unit. To update the card, go to the AEPS website:

<https://aeps2.ria.army.mil/commodity/guncard/index.cfm>

You'll need your AKO login and password to access the site.

NO DEXRON VI IN STRYKER TRANSMISSIONS

Mechanics, **do not** put Dexron VI in your Stryker transmissions. That fluid will ruin the seals and seal rings in 3000-, 4000-, AT-, MT-, HT- and CLT-series Allison transmissions. Dexron III is no longer available, so use TES 295 as a replacement in Stryker transmissions. Currently, that transmission fluid comes only in 55-gal drums with NSN 9150-01-551-2796.

M1070/M1074/M1075 Tow Shackle NSN

Use NSN 4030-01-539-5345 to get a 17-ton tow shackle for the HET and PLS. This NSN replaces the BII 13-ton tow shackle shown as Item 33 on Page B-11 of TM 9-2320-360-10 for the HET; and the shackle shown as Item 28 on Page B-11 of TM 9-2320-364-10 for the PLS.

M149A1 TRAILER ELBOW

Use NSN 4730-00-253-5765 to get the 90-degree elbow behind the front faucets for the water trailer. This NSN updates the parts info shown for Item 16 in Fig 28 of TM 9-2330-267-14&P.

VALVE STEM CAPS

Prevent accidental air leaks by replacing missing tire valve stem caps. A new standard-size cap comes with NSN 2640-00-255-9346.

M9 ACE Roadwheel

The earthmover's rubber roadwheel, NSN 2530-01-361-1764, is no longer available in the Army's supply system. Instead, the **only** roadwheel you can use is polyurethane that comes with NSN 2530-01-462-5062. If your ACE has a rubber roadwheel and you need another to go with it, order two polyurethane roadwheels. Do **not** mix different roadwheels on the same roadwheel arm.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?