


# Data Loading for Avionics

THE REMOTE  
FILL PANEL  
IS OUT.

AVIM CAN FIX  
THAT PROBLEM,  
BUT YOUR ANCD  
CAN STILL GET  
THE JOB DONE!




Crewmen, having problems entering data into avionics equipment using your Black Hawk's remote fill panel? Hold one before you yell for AVIM to start replacing avionics components.

Your radios, COMSEC, GPS or other avionics components, like the KY-58, may not be defective. You do need AVIM to check for broken wires or cables, and bad connections. And don't forget to check the remote fill panel.

If the remote fill panel is having problems, you can still load frequencies and data into each component separately using the automatic net control device (ANCD). When your SINCGARS, UHF radio, FM radios and GPS are configured, your mission can go on.

If remote fill panel is not working, load devices directly



ANCD device can be hooked to the fill ports

