

Return GBS Parts



Dear Editor,

Without the return of unserviceable assets, a damaged Global Broadcast Service (GBS) AN/TSR-8 Receive Suite, NSN 5820-01-530-6498, will never be repaired.

You must—**MUST**—turn in unserviceable parts so they can be repaired and returned to stock. Otherwise, the supply pipeline dries up and so does the GBS mission.

Here are some of the much-needed items:

Name	NSN
COMSEC interface tray	5810-01-529-3613
Interface unit, auto (IRD)	7025-01-529-0642
Digital computer system (laptop)	7010-01-528-9891
Common antenna group (feedome assy)	5985-01-530-2371
Antenna pedestal support (motor assy)	5985-01-530-1552
Antenna support group (tripod hub)	5985-01-530-2368
Antenna pedestal support (tripod assy)	5985-01-530-2369
Control receiver (STRC)	5895-01-530-1058
W-3 power cable	6150-01-530-1909
W-5 special cable	6150-01-530-8289
W-6 special cable	5995-01-530-1905

ILS GBS Manager
Ft Mormouth, NJ

Editor's note:
Thanks, _____,
for this vital
"heads up."
Soldiers, if you
don't turn parts
in for repair, it
won't be long
until parts are
not available.