



### M984 Wrecker Cable Assembly

Use NSN 6150-01-282-1182 to get the remote-control cable assembly for the wrecker's HIAB crane (right side under cargo body). This NSN replaces the one shown as Item 3, Page B-3 of TM 9-2320-354-10.

### M915 Armored Doors NSN Corrections

If you've ordered armored doors for your unit's M915A3P1, M915A2P1, M916A3P1, M917A2P1, M915A4P1, M917A1P1, M916A1P1, and M916A2P1 trucks with a Simula armor kit, you probably already know that the NSNs and part numbers listed for Item 17 of Fig 4 in TB 9-2320-302-13&P-1 are reversed. Use NSN 2540-01-533-7510 (PN 0257040002-00) to get the right hand door assembly, and NSN 2510-01-533-9728 (PN 0257040001-00) to get the left hand door assembly. Make a note until the TB is updated.

### AN/PSC-5 SPITFIRE ENHANCED CONTROLLER RECEIVER-TRANSMITTER

The AN/PSC-5 Spitfire enhanced controller receiver-transmitter, NSN 5895-01-498-2524, has been upgraded and given a new NSN. Order this upgraded receiver-transmitter with NSN 5895-01-541-6805. If you have an unserviceable receiver-transmitter that has not been upgraded, turn it in and it will be repaired and upgraded.

### SOLAR SHIELDS ARE COMING

Shadow units, keep your eyes peeled. The AMCOM PEOAVN is working a plan to field solar shields to protect the wings of your Shadow 200 RQ-78 Tactical Unmanned Aircraft System (TUAS) from the blazing sun.

If you've been using sleeping mats to shield the wings, remember they were only a substitute, not the primary equipment. The shield kit consists of six wing clips and two foam pads. Store the pads flat, not rolled up.

Solar shields minimize fuel loss through the fuel relief valve on the wing tip. Fuel loss is caused by fuel expansion from heat. The lost fuel is caught in the overflow container on the wing tip relief valve. If the valve fails to relieve the pressure, the wing can be damaged.

Make sure you check your operator's manuals on how to use the solar shields.

As fielding of the solar shield kits continue, make sure you add them to your unit's property book as part of the Shadow system. The shield kits are being fielded directly from the prime contractor. No NSN has been assigned to the shields. Order replacement parts through AAI Corporation's field representatives.

If you have questions, call (256) 313-5370, (256) 842-7196, (256) 313-5432 or (256) 313-5395. Or, you can email them:

@us.army.mil  
@us.army.mil

@peoavn.army.mil  
@us.army.mil

### M939/A1/A2 VALVE STEM

You can get the 5-ton truck wheel assembly's valve stem shown as Item c in Fig 292 of TM 9-2320-272-24P-1 by ordering NSN 4820-00-203-3260. Now you won't have to order Item 11 (that includes parts 12 thru 15) just to get the valve stem.

### PLS Air Filter and Air Drier Parts Kits

If your M1074 or M1075 PLS has a 4500 SP transmission, use air filter parts kit, NSN 4330-01-541-5349, and air drier parts kit, NSN 4440-01-493-3498, to maintain your truck. You can find both kits in TB 9-2320-364-13&P-3. Keep this in mind when it's time for service.

### AN/PYQ-10(C) SIMPLE KEY LOADER BATTERY CHARGER COMPONENTS

The battery charger assembly, NSN 6130-01-548-1505, for the AN/PYQ-10(C) simple key loader, NSN 5810-01-517-3587, has three components that can be ordered separately. If you need just the charger, order it with NSN 6130-01-525-1640; the power cord comes with NSN 6150-01-551-3064; and the AC/DC adapter with NSN 6130-01-551-3902.

### STATEMENT OF OWNERSHIP, MANAGEMENT AND CIRCULATION

Title of Publication:

PS, The Preventive Maintenance Monthly  
Publication No. 341-0950

Date of Filing: 28 Sept 07

Frequency of Issue: Monthly

No. of Issues Published Annually: 12

Annual Subscription Price:

Domestic \$45.00 Foreign \$63.00

Complete Mailing Address of Publication:

USAMC Logistics Support Activity, PS Magazine  
5307 Sparkman Circle, AMXLS-AM  
Redstone Arsenal, AL 35898-5000

Complete Mailing Address of Headquarters or

General Business Office of Publisher:

Department of the Army  
The Pentagon

Washington, DC 20310

Publisher: Department of the Army

Editor: W. RICHARD MORRIS

Managing Editor: VACANT

Known Bondholders, Mortgagees, and Other Security Holders  
Owning or Holding 1 Percent or More of Total Amount of Bonds,  
Mortgages, or other Securities: None

Tax Status: The purpose, function, and nonprofit status of this  
organization and the exempt status for federal income tax purposes  
has not changed during the preceding 12 months.

Extent and Nature of Circulation	Last year	Last issue (Oct 07)
a. Total # copies	68,531	63,580
b.(1) Subscriptions	66,651	61,673
b.(4) Other USPS	100	100
c. Total paid distrib	66,751	61,773
d.(3) Free through USPS	192	60
d.(4) Other free	317	600
e. Total free	509	660
f. Total distribution	67,260	62,433
g. Copies not distributed	1,271	1,147
h. Total	68,531	63,580
i. Percent paid	99.24%	98.94%

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life <sup>right now</sup> on  
the Condition of Your Equipment?