

**ORDERING SOLUTION FOR TRAILER LIGHT AND BRAKE TESTER**

On page 61 of PS 659 (Oct 07), we gave you an NSN for a trailer light and brake tester, but that NSN is no longer valid. Still want the tester? You can get it through local purchase. The item manager recommends going through Lite Check, Inc., in Spokane, WA, at (800) 343-8579 or email [info@lite-check.com](mailto:info@lite-check.com) Get more info at this website: [www.lite-check.com](http://www.lite-check.com)

**DECIDE ON LIFE**

Too many soldiers are dying needlessly from preventable accidents. The Army provides two pocket-sized tools to help reduce accident injuries and death. The *Accident Risk Assessment for Individuals* helps soldiers assess their personal risk. The *Leader's Accident Risk Assessment of Subordinates* helps supervisors assess their soldiers' risks. The tools are available on the Combat Readiness Center/Safety website under Awareness Information: <https://crc.army.mil/riskassessments>

**M3 Tripod T&E Pin NSN Change**

The NSN for the quick-release pin used on the M3 tripod traverse and elevation mechanism has changed to NSN 5315-01-529-9820. Make a note of this on WP 0145 00-3/4, Item 12, in TM 9-1005-245-13&P until the TM is updated.

**M249 SHORT BARREL BFA**

Gunners can now order a blank firing attachment (BFA) for their M249 machine gun's short barrel with NSN 1005-01-537-0491.

**Non-chromate Aircraft Primer NSNs**

GSA has just assigned NSNs to some newly-developed non-chromate primers for military aircraft. These two-component primer coatings are corrosion-inhibiting and chemical resistant, but do not include potentially toxic chromium.

NSN 8010-01-	MIL SPEC	Class	Size
555-3386	MIL-PRF-23377	Type 1, Class N	1-qt
555-3381	MIL-PRF-23377	Type 1, Class N	1-gal
555-3383	MIL-PRF-23377	Type 2, Class N	1-gal
555-3388	MIL-PRF-85582	Type 1, Class N	1-qt
555-3385	MIL-PRF-85582	Type 1, Class N	1-gal

**M1117 ASV Parts and Help**

Use NSN 2520-01-533-1518 to get the universal joint parts kit for the armored security vehicle (ASV). This NSN replaces the one shown as Item 18 in Fig 9-1 of TM 9-2320-307-24P. Use NSN 5305-01-437-4384 to order the turret mounting bolt, Item 5 of Fig 19-1. The NSN listed in the TM gets the wrong bolt. If you have questions, comments or suggestions about the M1117, email: [ASV@acom.army.mil](mailto:ASV@acom.army.mil)

**M939-SERIES TRUCK ABS TROUBLESHOOTING**

Need a troubleshooting tool for the anti-lock brake system (ABS) on your M939-series trucks? Order the infocentre diagnostic box using NSN 5895-01-515-9443. Check out Page 14 of PS 646 (Sep 06) for more information: <https://www.logsa.army.mil/psmag/archives/PS2006/646/646-14.pdf>

**TANK TOOL KIT T57366 OBSOLETE**

Because tool kit T24523 (Shop Equipment, Artillery Maintenance, Set N, Less Power, NSN 4933-00-754-0704) is almost identical to tool kit T57366 (Tank Turret and Artillery Mechanics Supplemental, NSN 4931-01-155-5307), the Army is making T57366 obsolete. The three T57366 tools that were not part of T24523 have been added to T24523.

The three tools added are:

- dial indicator holder, NSN 5120-00-390-5446
- dial indicator, NSN 5120-00-227-8840
- torque wrench, NSN 5120-00-221-7983

Units will soon be asked to turn in T57366 tool kits.

**HEMTT Tow Bar Light Harness**

Need the tow bar light harness for your M984 wrecker? It's shown as Item 1 in Fig 139 of the HEMTT IETM (EM 0232), but you can't get the right part using the NSN and part number that are listed. So until this problem is fixed, order it directly from the OEM, OshKosh Truck Corporation, at (920) 233-9522.

**New NSN for M1089's Pressure Switch**

Stop using NSN 5930-01-384-1534 to order a new pressure switch for your M1089 FMTV wrecker. Use NSN 5930-01-529-6304 instead. The new NSN also brings a CD with instructions for calibrating the crane in the field. And you won't have to supply the model and serial number to the manufacturer for calibration anymore.

**SATS Generator RESET POCs**

Generators that are part of the standard automotive tool set (SATS) can be turned in for overhaul through the RESET program in either SWA or your home station through these POCs:

- Kuwait, [@kuwait.swa.army.mil](mailto:@kuwait.swa.army.mil), DSN 318-430-4654, 011-965-389-4654
- East coast, [@us.army.mil](mailto:@us.army.mil), DSN 236-7153, (910) 396-7153
- Midwest, [@us.army.mil](mailto:@us.army.mil), DSN 663-2628, (254) 553-2628
- West coast and Pacific, [@us.army.mil](mailto:@us.army.mil), DSN 315-456-2774, (808) 656-2774

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

**Would You Stake Your Life <sup>right now</sup> on the Condition of Your Equipment?**