


Stryker...


AVOID THE SHACKLE CRUNCH

CRUNCH



If the shackles are installed with the retaining nut and cotter pin facing inside, the ramp could hit them as it's lowered.

To prevent the damage—and the noise—make sure the retaining nut and cotter pin are installed facing away from the ramp. Then double-check the shackles as part of your before-operation PMCS.



M1A1 AIM Tank RHNB

Use NSN 6110-01-514-7369 to order a redesigned hull networks box (RHNB) with container (NSN 8115-01-509-8851) for your M1A1 AIM tank with embedded diagnostics. The NSN listed as Item 1 in Fig 153 of TM 9-2350-264-24P-1 has the wrong supply class. Make sure you use the container when returning an unserviceable RHNB to prevent damage during transport. The RHNB, NSN 6110-01-517-1380, without a container is a terminal item, but is still available until stock is depleted.