

TRANSMISSION AND FREEWHEEL OIL FILTERS

YOU GOTTA
CHECK THE HOLE
PATTERN ON MY
FILTER UNIT.

YEP!
YOUR
FILTER
HAS 65
HOLES,
SO
YOU'RE
GOOD!




Mechanics, inspect your Kiowa Warrior's transmission and freewheel oil system filter, NSN 4730-01-214-1465, to make sure you have the right configuration.

Examine the filter unit screen hole pattern. If it doesn't have at least 65 holes, replace it with the correct filter.


The filter unit will not affect the normal operation of your bird, but the AMCOM headshed wants the incorrect filters replaced at the unit's earliest convenience. They put out a maintenance information message (MIM) OH-58D-MIM-2006-011 as a heads-up to units that the part was incorrectly manufactured.

To receive the correct filter, order it through normal supply channels.

If the oil filter unit on your bird has a minimum of 65 holes, then your aircraft is good to go. You can reference the part in EM-0256, IETM 1-1520-248-23P, Fig 89, Item 103.



Minimum
of 65 holes
is required



Fewer than 65
holes? Remove
from service