

Correct AN/PEQ-15 NSN

We steered you wrong on page 18 of PS 661 (DEC 07) on the NSN for the new AN/PEQ-15 target pointer. The correct NSN is 5855-01-534-5931. The POC for questions about the AN/PEQ-15 has changed. Now contact [redacted] at DSN 793-1674, (309) 782-1674, or email: [@us.army.mil](mailto:us.army.mil)

Mask Canister Website Correction

The website address for checking CBRN equipment shelf life that we gave you on Page 60 in PS 665 (Apr 08) was wrong. It should be <https://jacks.jpeocbd.osd.mil/>

Need Hellfire Help? Call JAMS

If you fire Hellfire missiles, you need to remember the JAMS War Room next time you get in a jam. JAMS stands for Joint Attack Munition Systems and their war room has a 24/7 hotline to help you with Hellfire problems. Contact JAMS War Room at DSN 788-0295, (256) 842-0295, or email: [@us.army.mil](mailto:us.army.mil)

AFS Replaces GVO, BVO Boots

The alternative footwear solution (AFS) is replacing the green vinyl overshoe (GVO) and black vinyl overshoe (BVO) as the chemical protective boot. The AFS is a lightweight chemical and biological agent protective overboot made of compounded butyl rubber. It should provide 24 hours of protection when exposed to chemical agents. AFS can be worn for up to 45 days. For sizes, NSNs, and general info on AFS, go to: <https://aeps2.ria.army.mil/sbcom/gtw/intro.cfm>

WD CARC SPOT PAINTING TB

The newly revised TB 43-0242, *WD CARC Spot Painting* (Dec 07), is now available. The TB covers the how, when and where of spot painting with the new water dispersible CARC. It also includes NSNs for new WD CARC products such as aerosol sprays and bottles with roller-top and brush-top applicators. You'll find it on the LOGSA ETM website: <https://www.logsa.army.mil/etmpdf/files/080000/084390.pdf>

M939-SERIES TRUCK WHEEL SEALS

There's a new NSN and part number for the plain encased seal used on your M939-series truck front and rear wheel assemblies. It's shown as Item 19 in Fig 293 and Item 13 in Fig 295 of TM 9-2320-272-24P-1. Update your TM using NSN 5330-00-740-9550 and part number 7979349.

New Screw for M16 Rifle Rail

The socket head cap socket screw, NSN 5305-01-453-2725, that holds the upper rail to the M16A4 rifle and the M4/M4A1 carbine has been replaced with an improved slotted head screw, NSN 5305-01-540-4805. Unlike the old screw, the new one can be reused. Note the change on Pages 39-23 and 39-25 in TM 9-1005-319-23&P.

MRAP TRAINING AT RED RIVER ARMY DEPOT

Need mine resistant ambush protected (MRAP) vehicle driver's and maintenance training? Get it at Red River Army Depot through MRAP University. This training is available for all services, LARs, RRAD maintenance personnel, LOGCOM and OEM field service reps. The length of training depends on what training you need and your skill level before attending. For more information, contact

MRAP University site lead: DSN 829-4905, (903) 334-4905, or email:

[@conus.army.mil](mailto:conus.army.mil)

Or reach : DSN 829-4913, (903) 334-4913, or email:

[@us.army.mil](mailto:us.army.mil)

LBS Replaces M30 Boresight

When it's time to replace the M30 boresight for your rifles or machine guns, don't order another M30. The laser bore light system (LBS), NSN 5860-01-471-2091, replaces the M30 and costs \$400 less. The LBS has a LIN of FA6000.

One Left Out!

We blew it on the email address of [redacted] in our article about FLIR parts on Pages 40 and 41 of PS 665. We left a 1 out! email is:

[@us.army.mil](mailto:us.army.mil)

AOA GRADER WHEEL ASSEMBLY

Use NSN 2530-01-549-6588 to get the wheel assembly for the 130G road grader with add-on-armor (AoA). The assembly includes a new 16-ply rated tire that can handle the added weight of the armor. Make a note until the NSN is added to Fig 186 of TM 5-3805-261-23P.

HYEX BII UPDATE

Make a note of these NSNs until they are updated in the BII list on Pages B-3 and B-4 of TM 5-3805-280-10:

Item	Name	NSN
3	Wrench, 3-in	5120-01-376-5124
7	Pliers, vise grips	5120-01-400-0314
8	Hammer, wood handle	5120-01-434-9158
10	Gun, grease, lever action 18-in flex hose	4930-00-640-4090
13	Fire extinguisher (new item)	6830-00-555-8837

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?