

Turn in IBAS Unserviceables



The Army is running out of Bradley A3-series improved Bradley acquisition system (IBAS) repair parts because units aren't turning in unserviceable IBAS components.

The depot doesn't have IBAS components to repair and the supply pipeline goes dry. The Army is forced to purchase new replacement parts, which costs a whole bunch of money.

So if you have any IBAS items (weapon system code EH) that are considered unserviceable/repairable (condition code F), turn them in NOW!

These items are in especially short supply:

| Item | NSN | P/N |
|--|------------------|----------|
| Periscope head assembly | 1240-01-442-4825 | 13588710 |
| Monocular assembly | 1240-01-464-1068 | 13588680 |
| Xenon tracker assembly | 1240-01-466-4050 | 13588692 |
| Missile control subsystem | 1430-01-462-8506 | 13588703 |
| Laser shutter assembly | 5855-01-462-8522 | 13588672 |
| Collimator, infrared | 5855-01-462-9048 | 13588681 |
| Circuit card assembly, IBAS frame buffer | 5865-01-462-1739 | 13588707 |
| Lower target acquisition subsystem | 5865-01-462-8513 | 13588676 |
| Target acquisition subsystem | 5865-01-462-8514 | 13588671 |
| Target acquisition system block 1 | 5865-01-537-0124 | 13620293 |
| Lower target acquisition system block 1 | 5865-01-537-0134 | 13620294 |
| Circuit card assembly, quad C40 | 5998-01-462-8510 | 13582747 |
| Circuit card assembly, missile interface | 5998-01-462-8512 | 13588709 |
| Circuit card assembly, range logic card | 5998-01-462-9833 | 13492680 |
| Circuit card assembly, power supply assembly | 6130-01-473-1472 | 13586629 |
| Biocular display assembly | 7025-01-463-4586 | 13588679 |

All of these items have a recoverability code of D.