

IN-LINE FUEL FILTER FIX




DON'T CALL A **PLUMBER** IF YOUR M939A2'S SMALL IN-LINE FUEL FILTER GETS **CLOGGED!**

ORDER A **BIGGER FILTER** INSTEAD.

Using the bigger filter should fix the problem of clogging, which stops you in your tracks. NSN 4930-01-387-1147 brings the bigger and better in-line fuel filter kit.

By the way, this is the same filter that is used on older M939s. The filter element alone comes with NSN 2910-00-152-2033.



Replace this filter with a bigger one

So get your unit mechanic to make the initial changeover on the vehicle. Instructions come with the kit.



Filter element alone comes with NSN 2910-00-152-2033

HMMWVs...

Longer Lasting Geared Hub Seal

Dear Editor,

Our unit uses the old-style inner geared hub seal, NSN 5330-01-180-9099, on our HMMWVs. They work well enough, but we've found that another geared hub seal, NSN 5330-01-456-3884, lasts longer. It costs more, but it's worth it for us in the long run.

SFC
Ft Sill, OK

Editor's note: Your HMMWV parts manuals don't list the longer-lasting geared hub seal. If your chain of command doesn't mind paying more, the new seal may pay off for your unit. Thanks for the tip, Sergeant.