

Up-Armored
HMMWVs...

OUT WITH THE OLD REAR CONDENSERS

SEEN DAMAGE ON THE REAR AIR CONDITIONER CONDENSERS ON YOUR M1151, M1152, AND M1165 BASIC AND -A1 UP-ARMORED HMMWVs?


WISH YOU HAD MORE CLEARANCE IN THAT AREA?

YOU'RE NOT ALONE.


Problems in the field led TACOM LCMC to develop a new rear condenser. It allows for more clearance and has a beefed-up closeout panel. That should curb damage.

The original rear condensers, NSN 4130-01-537-4847 and NSN 4130-01-536-5561, are no longer available. But you can get the new condensers, closeout panel and related hardware in new upgrade kits that the truck headshed assembled.

New rear condenser allows for more clearance and has beefed-up panel



ORDER THE LEFT-HAND REAR CONDENSER KIT USING NSN 2540-01-558-3448, AND THE RIGHT-HAND REAR CONDENSER KIT USING NSN 2540-01-558-3450.



AND MAKE A NOTE OF THIS IN THE TM UNTIL IT GETS UPDATED.