


Returning Unserviceable RTs



The AN/TSQ-158, enhanced position location reporting system (EPLRS) radios,

RT-1720B(C)/G, NSN 5820-01-457-0014

RT-1720C(C)/G, NSN 5820-01-457-0012

RT-1720D(C)/G, NSN 5820-01-490-7019

RT-1720E(C)/G, NSN 5820-01-490-7025

RT-1720F(C)/G, NSN 5820-01-470-7018

RT-1720G(C)/G, NSN 5820-01-514-1408

are built and maintained by Raytheon Co.

Previously, these radios were repaired under a repair and return program. This is no longer so.

If you have a non-working radio that needs to be turned in to repair for depot level work, fill out a DD Form 1348 MILSTRIP requisition to request disposition.

The item manager will then direct the RT to be shipped to Raytheon using DoDAAC CG001Q/RIC:C1G through the Army standard

supply system. They will include a copy of the DD Form 1348 and a completed DD-1149 and DA-2407 or DA-5504. You'll receive unserviceable credit for the RT.

Submit a funded DD Form 1348 MILSTRIP for a replacement radio. You'll be charged the AMDF price for it.

If you have questions concerning this process, call the EPLRS inventory manager at C-E LCMC at DSN 992-1852 or (732) 532-1852. Or email:

@us.army.mil

@us.army.mil

@us.army.mil