

M261 Rocket Launcher...

TM Misleading on Current Check

HEY, THAT TM IS
WRONG ON MY STRAY
CURRENT CHECK.

WE BETTER
TELL PS
SO IT CAN
LET THE
REST OF
THE ARMY
KNOW!


Dear Editor,

Illustration 7G1X_OOX101A for the M261 rocket launcher stray current check in TM 1-1520-Longbow Apache on EM O126 shows the igniter arm in the raised position for the stray current check.

Actually, the igniter arm should be in the down (fire) position for the check. Please let other aviation crews know so they can correct their TMs.

SSG
8/229 Avn Regt
Ft Knox, KY

Igniter arm should be in the down
(fire) position for stray current check



*Editor's note: You're absolutely right, Sergeant.
This was corrected in the last change to the TM.*

CH-47D/F...

SPECIAL TOOLS FOR A BIG BIRD

HAVE YOU EVER WONDERED
WHAT SPECIAL TOOLS YOU
NEED FOR YOUR CHINOOK?
STOP WONDERING!

EVERY SPECIAL TOOL
YOU'LL EVER USE ON THE
CHINOOK WITH A T55-GA-
714A ENGINE IS NOW LISTED
IN TB 1-1520-240-20-168.

THE TB CONTAINS THE
RECOMMENDED QUANTITIES
OF EACH TOOL NEEDED
ON THE AIRFRAME AND
THE ENGINE FOR THE
GENERAL SUPPORT AVIATION
BATTALION (GSAB) AND
THE AVIATION SUPPORT
BATTALION (ASB).