

IS THERE ANYTHING BETTER THAN BUILDING A SNOWMAN IN WINTER?

YES! DOING PM!

Connie's ★ POST ★ SCRIPTS

HEMTT LHS SWITCH KNOB

Your HEMTT's load handling system rotary switch knob is shown as Item 13 in Fig 2001 of EM 0232, TM 9-2320-315-14&P. But the NSN listed is obsolete now because the knob is no longer available by itself. Get a replacement switch assembly, which includes a new knob, using NSN 5930-01-372-9489 and part number 3533104.

HMMWV V-Belt Inversion Works

Having problems with the adjustable link V-belt used on your HMMWV's serpentine belt system and found in your BDAR kit? You know, it's the V-belt that has a tendency to walk off the pulleys.

You can fix this by inverting the V-belt, a solution approved through the SMART suggestion program. Putting the flat side against the serpentine pulleys is the trick. Testing shows this allows the V-belt to perform better and it's less likely to wander off the pulleys.

DEXRON VI OK for HMMWV

All HMMWV transmissions and power steering systems are compatible with DEXRON VI fluids. And you don't have to flush your transmission or steering system before adding DEXRON VI to it. That's because testing proved that mixing DEXRON III and DEXRON VI won't degrade the transmission or steering system performance.

Keep this info handy until HMMWV technical manuals and lubrication orders are updated.

M777-SERIES HOWITZER SOLAR CHARGER

Use NSN 6130-01-521-1387 to get a new solar charger/AC charger (w/o case, with solar panel) for your M777-series towed howitzer. NSN 6130-01-521-1386, which is listed as Item 76 on Page B-16 of TM 9-1025-215-10, gets the wrong item.

CHECK FMTV ANNUAL SERVICE KITS FOR FAULTY AXLE SEAL

A faulty axle seal, NSN 5330-01-360-5252, has been mistakenly included in some FMTV annual service kits: NSN 2590-01-528-7507, NSN 2590-01-528-7239, NSN 2590-01-533-6748, NSN 2590-01-533-6745, NSN 2590-01-528-7508, and NSN 2590-01-528-7243.

The seal, made by YEI, has an inside diameter that's too small. If you find any of these seals in these kits, don't try to use them. Use all the other kit components and submit a PQDR for the kit. Request credit for the seals; DFAS will allow it. Then order just the correct Meritor seals from DLA using NSN 5330-01-360-5252.

Turn the wrong seals in to DRMO or destroy them using local SOP.

M915A3 Sending Unit

Use NSN 6685-01-081-9721 to get the sending unit for the tractor truck's transmission cooler line that's shown in Item 9, Fig 93 of TM 9-2320-302-24P.

V-Belt for M35A3

NSN 3030-01-460-1030 gets the 2 1/2-ton truck's V-belt shown as Item 8 in Fig 49 of TM 9-2320-386-24P. The NSN shown in the TM for the V-belt is wrong.

M149A2 WHEEL BEARING NSN

NSN 3110-00-100-5951 gets a complete wheel bearing assembly for the water buffalo. The NSN shown as Item 16 in Fig 17 of TM 9-2330-267-14&P gets only the tapered roller bearing.

TANK AND PUMP UNIT HOSES

Use NSN 4720-01-022-6016 to get the hose that connects the forward tank to the manifold on the mil design tank and pump unit. This NSN replaces the one shown as Item 1 in Fig 14 of TM 10-4930-236-13&P. NSN 4720-01-360-4360 gets the hose shown as Item 3 in the same figure.

Use Project Code 924 for MRAP Parts!

MRAP users, whenever you order parts to support your MRAP vehicle, use project code 924, not 9GJ, the code for OEF, OIF, and HOA. Code 924 also gives priority air transport for MRAP parts.

New M68 Sight Lens Cover

The M68 sight CompM2 lens cover has been replaced with the CompM4 lens cover. Order it with NSN 5895-01-549-5835 (p/n 11790).

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?