

Automated Integrated Surveying Instrument...

WHY AREN'T YOU WORKING TODAY?

YOU'RE WAY OFF!


MY BATTERIES ARE GOING, GOING, ALMOST GONE.

I'M TOO WEAK TO SURVEY.

Check Batteries Now!


Don't wait until you get to the field to find out if the internal batteries for your automated integrated surveying instrument (AISI) are working. Then it's too late to do anything about it. Check the batteries now. There are two ways to check:

- Look at the Trimble Battery replacement due date sticker just below the distance meter head. If the due date has passed, you need new batteries.



Look at replacement due date sticker...

- If the sticker is missing, turn the power on and look for INFO 26 in the display. That means the batteries need to be replaced as soon as possible. If you continue to operate the AISI in an INFO 26 condition or with expired batteries, you risk total loss of the AISI memory and AISI failure.



...or check for INFO 26 in display

Unfortunately, you can't replace the batteries yourself. An authorized service center must do it.

To get instructions and approval for free AISI battery replacement, contact CECOM's at DSN 987-5472, (732) 427-5472, or email:

[@us.army.mil](mailto:us.army.mil)

He will need the serial number of your AISI.