



RECALL FOR CARBON MONOXIDE DETECTORS



IF YOUR UNIT HAS A FOOD SANITATION CENTER MODEL 2 (FSC-2), NSN 7360-01-496-2112, YOU NEED TO READ TACOM SAFETY-OF-USE-MESSAGE (SOM) 08-007.

THE SOM SAYS THAT *SOME* FSC-2s HAVE A CARBON MONOXIDE (CO) GAS MONITOR WITH A FAULTY CO DETECTOR.

AND A FAULTY DETECTOR *CAN'T* WARN YOU WHEN UNHEALTHY LEVELS OF CO ARE LURKING IN THE AIR.



The manufacturer has issued a product recall for detectors in FSC-2s with the following serial numbers:

8301 through 8323, 8325, 8327, 8329 through 8337, 8344, 8350, 8359, 8374 through 8377, 8380, 8386 through 8388, and 8394.

For the complete story, get TACOM SOM 08-007. It covers inspection, manufacturer's POC, replacement parts, compliance reporting and more. The SOM's on the Army Electronic Product Support (AEPS) website:

https://aeps2.ria.army.mil/commodity/soum/tacom_wn/08/soum08-007.html

To log in, you'll need your AKO user name and password or your common access card (CAC) and PIN.