



## 120mm Mortar Dust Cap

A rubber dust cap is now available for your 120mm mortar that snaps over the bore to keep out dust and moisture. Order the dust cap with NSN 1015-01-209-3482. The cap has been added to the AAL in TM 9-1015-250-10. The cap doesn't work with a mortar equipped with a blast attenuator.

## AIDPMO Reassigned to SDDC

If you haven't heard, the Army Intermodal and Distribution Platform Management Office (AIDPMO) doesn't fall under LOGSA anymore. On 1 Oct 08, it became a part of the Surface Deployment and Distribution Command (SDDC). You may be wondering if you can still use those numbers you had for AIDPMO. You can because they're still at Tobyhanna and the POC info hasn't changed.

## AIRCRAFT JACK STAND

On page 39 of PS 674 (Jan 09), we told you to contact the AMCOM headshed for maintenance issues on the 3-ton jack stand, NSN 1730-01-541-3186. For maintenance problems, you can now consult TM 1-1730-270-13&P, *Identifying Technical Publication Sheet for Commercial Manual (3 Ton Tripod Jack) Part Number/NSN: Model 9775-010/NSN 1730-01-541-3186*. It's a commercial manual. The TM is available on LOGSA's ETM website. You can also order hard copies on your 12-series publications account.

## TM Available for Sniperscope

The AN/PVS-29 night vision sniperscope, NSN 5855-01-567-9243, now has its own TM, TM 9-5855-1916-13&P. The -29 was formerly called the AN/PVS-26, NSN 5855-01-538-8121. Its ZLIN will remain Z01240. You can access the TM at the ETM site:

<https://www.logsa.army.mil/etms/online.cfm>

Your pubs clerk can order hard copies of the TM at

<https://dol.hqda.pentagon.mil/ptclick/index.aspx>

## New ECM for M915A2/M916A1 Tractor Trucks

Get the new electronic control module (ECM) for the DDEC IV engine in M915A2 and M916A1 tractor trucks with NSN 2920-01-561-7722. Its wiring harness comes with NSN 5995-01-562-0522. The ECM comes programmed and ready for installation.

## M871A3 AXLE PARTS

NSN 5310-01-499-5416 now gets the keeper arm and locknut for the axle on the 22 1/2-ton semitrailer. They're presently shown as Items 9 and 10 in Fig 17 of TM 9-2330-326-14&P. They are no longer available separately, so make a note until the TM is updated.

## M1A1 AIM 5A Tank Sidecar SMR Code

If a sidecar assembly, NSN 6625-01-497-1915, fails on your M1A1 AIM 5A (situational awareness) tank, don't toss it in the trash. The sidecar assembly's SMR code has recently changed to PAFLL. That means it's repairable by a special repair activity and should be turned in.

## Access TM Changes ONLINE

The much requested ETM change access feature is online! You can access and download an individual change to a manual independent of the manual itself. The feature works for changes dated 1 Aug 08 or later, if available. Use the URL below to access ETMs Online on the Logistics Information Warehouse (LIW) website. Click through to its search page, enter your search criteria, click on Search, then click on the desired underlined change number. When the change opens, you can download or print it. The URL is:

<https://liw.logsa.army.mil/index.cfm?fuseaction=home.main>

## SMOKE GRENADE LAUNCHERS WANTED

If your unit has any of the following smoke grenade launchers and doesn't need them, please turn them in regardless of their condition. The Army needs them.

- M239, NSN 1055-01-015-0874
- M250, NSN 1055-00-000-0138
- M257, NSN 1055-01-070-1213
- M243, NSN 1055-01-059-0560
- M259, NSN 1055-01-107-7501

For turn-in info, contact TACOM at DSN 793-1954, (309) 782-1954, or email:

[@us.army.mil](mailto:us.army.mil)

## Rhino FSR Update for Iraq

Page 17 of PS 679 (Jun 09) provided a list of POCs for PM IED Defeat/Protect Force Field Service Representatives (FSR) in Southwest Asia. The contact information for Iraq has changed. Here's the updated info:

### Baghdad

[@iraq.centcom.mil](mailto:iraq.centcom.mil)

[@iraq.centcom.mil](mailto:iraq.centcom.mil)

Cell 07906402306

DSN 485-0312

MMCS: 312-987-5130, Option 1, ext. 6824/6825

### Balad

[@mmcs.army.mil](mailto:mmcs.army.mil)

[@mmcs.army.mil](mailto:mmcs.army.mil)

Cell 07810357584

DSN 312-987-5130, Option 1, ext. 6271/6283

### Mosul

[@mmcs.army.mil](mailto:mmcs.army.mil)

[@us.army.mil](mailto:us.army.mil)

Cell 07810025526

DSN 312-987-5130, Option 1, ext. 5850

### Q-West

[@iraq.centcom.mil](mailto:iraq.centcom.mil)

[@iraq.centcom.mil](mailto:iraq.centcom.mil)

Cell 07706610688

DSN 318-827-6255

### Tikrit

[@mmcs.army.mil](mailto:mmcs.army.mil)

[@mmcs.army.mil](mailto:mmcs.army.mil)

Cell 07705482672

DSN 312-987-5130, Option 1, ext. 8560/8567

The information for Afghanistan is still good.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life <sup>right now</sup> on the Condition of Your Equipment?