


AN/PSS-14 Mine  
Detector...



**Train  
Free to  
be UMT**



UMT stands for unit master trainer. Every unit that uses the AN/PSS-14 needs a UMT to keep your unit's operators licensed to use the detector. A change to AR 600-55, *The Army Driver and Operator Standardization Program*, will soon be published that will require mine detector operators to be licensed and then be re-certified every six months.

UMTs train new operators and re-certify trained ones. Unit master trainers must be sergeants and above who have already attended the operator's course and been certified to operate the detector. The 40-hr UMT course provides additional instruction on the AN/PSS-14, including operating the sweep monitoring system (SMS) and establishing and running a unit training program.

If your unit has been fielded the AN/PSS-14 but doesn't have a UMT, you can schedule a free visit from the mobile training team (MTT) for UMT training. To get the free training, you must act fast. Soon UMT training will become part of the Army's regular training program and units will have to send NCOs TDY for UMT training.

To schedule UMT training, contact John Sullivan at (573) 329-8706 or at DSN 676-0131 and ask for extension 329-8706, or email: [leon.cdidumt@conus.army.mil](mailto:leon.cdidumt@conus.army.mil)