




Get Your XM107 Converted



There are still a few snipers that haven't had their XM107 sniper rifle converted to an M107 by having MWO 9-1005-239-55-1 applied.

The MWO adds a new bolt carrier pin and a cheek pad, modifies the charging handle and moves the set bump.

How do you tell if you have an XM107 and not an M82 or M107 sniper rifle? The XM107 has a full rail with a front sight that is not embedded in the rail. Most XM107s have "XM107" stamped on the receiver, although this isn't always true. If the rifle's serial number is lower than 7629, it's an XM107. If the XM107 has been modified, the "X" will be stamped out.




If you have an XM107, **don't try to send it to the manufacturer to have the MWO done.** You will just waste your time and the manufacturer's. **You must go through TACOM-RI for the MWO.** That's the only way.

If you have a local TACOM-RI logistics assistance representative (LAR), contact him for help on what forms you need to fill out and for shipping instructions for your XM107. No LAR? Contact TACOM-Rock Island at DSN 793-0926, (309) 782-0926, or email: @us.army.mil

Repair

If your XM107 or M107 ever needs repair, contact your TACOM LAR or the TACOM-RI phone numbers and email listed previously. They will give you instructions on how to send your rifle to the manufacturer for repair.


BE DOUBLE SAFE WITH SAFETY SLIDE



Dear Editor,

The safety slide on the MK 19 machine gun can be installed backwards if you're not careful. Then the weapon can fire even when it's set to safety, which could be a disaster. Armorers, before you let an MK 19 out of the arms room, make sure the tab on the safety slide is facing to the rear. That's the way it's supposed to be.

Tab should point to rear



Mr. M.E.
TACOM logistics assistance representative
Ft Benning, GA

Editor's note: This is a good check to add to your PMCS. Thanks for the tip.