



PUT YOUR BEST FOOT FORWARD



It's only natural, mechanics. When doing repair work in the engine compartment of a Stryker, most of your concentration is on what you're doing with your hands.

But where you place your feet needs attention, too.

A boot in the wrong place—say, on the thermal control manifold—is a big problem. Stepping on the manifold can loosen or even crack the seals on the two quick-disconnect couplings. Then you've got a hydraulic leak to fix and a big mess to clean up.

If you need a place to step on the engine, use the non-skid plate just to the side of the manifold of the CAT 3126 engine. Not only does that prevent damage, but you're less likely to slip and hurt yourself.

