

Test
Sets...

Turn in Serviceable DSESTS

WE'RE BEING TRANSFERRED, BUT THANKS FOR THE HELP YOU GAVE US TROUBLE SHOOTING OUR BRADLEYS.

HOPE YOU DO AS GOOD A JOB FOR THE NEXT UNIT WITH THIS MISSION.



DON'T WORRY, WE'LL DO OUR BEST.

THANKS FOR MAKING SURE WE GOT IN THE RIGHT HANDS BEFORE YOU LEFT!

Units are not turning in direct support electrical system test sets (DSESTS) when their missions terminate or transfer. That means the next unit assigned that mission can't carry out DSESTS testing.

DSESTS, which can't be procured, was fielded to perform off-vehicle testing of line replaceable units (LRU) and shop replaceable units (SRU) from the Bradley FVS and M1-series tank. A complete DSESTS comes in approximately 40 cases, along with ancillary equipment and fixtures.

The DSESTS consists of:

- general purpose interface assembly (GPIA), NSN 5998-01-382-7282
- operator interface unit (OIU), NSN 6625-01-225-8342
- DSESTS common resources (DRC), which includes the common function modules, NSN 6625-01-443-2478, and combined support functions module (CFSM), NSN 6625-01-559-2662, or the enhanced unit, NSN 6625-01-569-3614
- transfer standards adapter (TSA), NSN 6625-01-448-9832
- M1 tank Legacy and Bradley A2 ODS Legacy, NSN 6625-01-120-0764 (LIN T52849)
- M1 thermal imaging system (TIS), NSN 4931-01-263-7972 (LIN T92250)
- Bradley TOW system, NSN 6625-01-442-7490
- Bradley A3, NSN 6625-01-453-7394
- Common FLIR TIS, NSN 6625-01-443-8390
- Wolverine, NSN 6625-01-474-5713

Units should check to see if they have any of this DSESTS equipment. If you find any, do the self-tests described in the TM 9-4931-586-series TMs to see if the equipment is serviceable. Serviceable excess DSESTS equipment should be turned in to your property book officer. Serviceable DSESTS equipment should also be turned in to the property book officer if your mission is soon to be terminated or transferred. TACOM-RI will reissue the equipment to the units taking over the missions. All unserviceable DSESTS equipment should be submitted through the Automated Excess Return Process (FTE transaction).

If you have questions, contact TACOM-RI's Kelly Karcher at DSN 793-6094, (309) 782-6094, or email

kelly.karcher@us.army.mil

You can also contact Matisse Coffee at DSN 793-0718, (309) 782-0718, or email

sinclair.m.coffee@us.army.mil

or Barry Tabron at DSN 793-1901, (309) 782-1901, or email barry.tabron@us.army.mil