

## RG33L MRAP Transfer Gear Box

Use NSN 2590-01-535-6471 to get the transfer transmission assembly for the RG33L Plus and RG 33L HAGA Plus MRAP vehicles. This NSN replaces the one shown as Item 8 in Fig 65 of TM 9-2355-320-24P.

## TRAILER HOOK HANG-UP

If you read the trailer safety chain article on pages 11-13 of PS 673 (Dec 08), you may have encountered a hang-up with hook, NSN 4030-01-531-2978. That's because the NSN doesn't exist anymore! The only lunette trailer using this 1/2-in safety chain hook is the *now obsolete* M345. If your unit hasn't turned in the M345s to DRMO, order that hook when you need it using part number 1029835 and CAGE code 76257 on DD Form 1348-6. Or look for a hook for a 1/2-in chain at a local hardware store.

## LBS Left Out of M16 TM

The M16 rifle's TM 9-1005-319-23&P (Nov 08) accidentally left out the laser borelight system (LBS), NSN 5860-01-471-2091. The LBS replaces the M30 boresight, which **is** listed in the TM. The LBS is authorized by CTA 50-970 and can be ordered at the commander's discretion. If you need info on the LBS, see TM 9-5860-226-13&P, which can be found on LOGSA's ETM Online:

<https://www.logsa.army.mil/etms/online.cfm>

## M109A6 Paladin Antenna Replaced

The Paladin's PLGR antenna assembly, Item 1 in Fig 246 of TM 9-2350-314-24P-2, has been replaced by the DAGR antenna assembly, Item 1 in Fig 246A, NSN 5985-01-543-0177. This change has been made in Change 5 to the TM. Continue to use the PLGR antenna, but when you replace it, order the DAGR.

## MRAP RG33L Socket Screw

Use NSN 5305-01-547-4620 to get a socket-head screw for the MRAP RG33L Plus & HAGA Plus vehicles. This NSN replaces the one shown for the front wheel hub bolt, Item 7 in Fig 74 of TM 9-2355-320-24P.

## TACOM Battery Training Videos

TACOM recently introduced vehicle battery training videos. The topics include maintenance recovery issues, charging systems, reasons for battery failure, battery maintenance, safe handling, and battery testing. Check out these videos online:

<http://www.army.mil/news/2009/10/15/28860-tacom-battery-training-videos/>

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life <sup>right now</sup> on  
the Condition of Your Equipment?