


ROTOR DAMPER INDICATOR SERVICING



WP 0537 00 of TM 1-1520-237-23-7 gives the inspection criteria for determining whether you can service a damper indicator. Repairs to an indicator can be done within certain limits like the TM says. There are also procedures that tell you when the dampers must be replaced or are damaged beyond repair.

If you replace a damper indicator, you must use the locally-made damper indicator insertion and installation tools.

The instructions to make these tools are in Figs 165 and 166 of WP 1085 in TM 1-1520-237-23-20.

If you can't make the tools in the machine shop, all is not lost. You can order them from the manufacturer on a DD Form 1348-6. Enter "Damper Indicator Tool" for the part number. Use CAGE Code 55723. The tools cost \$150 dollars.

GET THEM DIRECT FROM...

Spectrum Associates Inc
183 Plains RD
Milford CT, 06461

OR CALL THEM...

(203) 878-4618

They are the folks who make the damper indicator, so you can bet your bottom dollar the tools will work.

