


# SIGHTS REQUIRE SPECIAL TURN-IN



**T**hree of the sights used on small arms contain radioactive material, which means you must follow special turn-in and shipping procedures for the sights. The sights are:

- M150 optical bore sight, PN TA31RCO-M150, NSN 1240-01-557-1897
- ACOG optical bore sight, PN TA31RCO-M4, NSN 1240-01-534-1114
- ACOG optical bore sight, PN TA31F, NSN 1240-01-514-8428

The turn-in procedures can be found in AEPS:

[https://aeps2.ria.army.mil/commodity/mam/tacom\\_wn/mim10-009.html](https://aeps2.ria.army.mil/commodity/mam/tacom_wn/mim10-009.html)

Before shipping one of the sights, your unit property book officer must contact the sight's manufacturer, Trijicon Inc, to get a return authorization (RA) number. Call Trijicon at (800) 338-0563 from 9 am to 5 pm EST or email:

[contractadministration@trijicon.com](mailto:contractadministration@trijicon.com)

Once you have an RA, your transportation officer can coordinate shipment of the sight by following part 173.424 in 49 CFR DOT regulation:

<http://frwebgate.access.gpo.gov/cgi-bin/get-cfr.cgi?TITLE=49&PART=173&SECTION=424&YEAR=1999&TYPE=PDF>

If you have questions, contact TACOM at DSN 793-0047, (309) 782-0047, or send an email:

[@us.army.mil](mailto:@us.army.mil)