


# Turn In Unserviceable STORMs



If you have unserviceable AN/PSQ-23 small arms integrated illuminators (STORM), turn them in ASAP. The Army needs to repair them and get them back in action.

To determine if your STORM is still under warranty, send the STORM's nomenclature, serial number, and a description of the malfunction or damage to [RETURNS@INSIGHT-TEK.COM](mailto:RETURNS@INSIGHT-TEK.COM) or call (877) 744-4803.

Black STORMS are NSN 5855-01-535-1905 and tan ones are NSN 5855-01-577-5946.

If you have unserviceable STORMS that are no longer covered by warranty, contact your local property book officer (PBO). He will report the STORM to the National Inventory Control Point (NICP) B14 using an FTE (report of excess), following the instructions in Chapter 7 of AR 725-50, *Requisition and Issue of Supplies and Equipment*.

The NICP will respond with final disposition instructions through an FTR (reply to report of excess), directing you to ship the STORM to a depot for repair. A replacement can be ordered from the NICP once the unserviceable STORM has been turned in.

