

# Connie's POST SCRIPTS

## ELECTRONIC GUN CARD REVISITED

The electronic gun card article on Pages 2-5 of PS 688 (Mar 10) needs two clarifications. First, Step 1 on Page 4 says to notify Team Armor whenever you transfer, turn in, store or send your equipment for rebuild or overhaul. That applies **only** to M1-series tanks. For other equipment, notify the appropriate POC listed at the bottom of Page 5. Second, the DSN for the mortar POC on Page 5 has an extra digit. The correct DSN is 786-8783.

## HMMWV Spring and Shock NSNs

Here are the spring and shock NSNs for M1151, M1151A1 (with B1 kit), M1152, M1152A1 (with B2 kit), M1165, M1165A1 (with B3 kit) and M1167 up-armored HMMWV suspensions:

Item	NSN
Front helical spring	5360-01-457-8029
Rear helical spring	5360-01-524-6029
Front shock service kit (shocks included)	2510-01-554-1785
Rear shock service kit (shocks included)	2510-01-554-1789

## HMMWV Traversing Gear Assembly

HMMWV GPK traversing gear assembly, NSN 5340-01-536-2054, has been replaced by an upgraded assembly, NSN 1005-01-563-4655. This upgrade should reduce the failures associated with the original assembly.

The new traversing gear assembly is a direct replacement for the original assembly, but the crank handles are different. The upgraded crank handle, NSN 5340-01-563-6839, fits into the gear shaft and is held in place with a quick-release pin. The original crank handle, NSN 5340-01-536-0999, fits over the gear shaft and is held in place with set screws.

## M4K RTFL Engine Warranty

Your rough-terrain forklift's engine re-power kit, NSN 2815-01-529-2006, comes with a one-year warranty. The warranty covers the engine when it's installed on the forklift—not when you receive the kit. Warranty paperwork comes with the kit, so fill it out ASAP after installation. If you lose a copy of the warranty, request a new one from:

CNH America LLC  
Attn: Defense Products Group (M4K)  
621 State Street  
Racine, WI 53402

Make sure you include the engine's serial number and date when it was installed.

## Return CBPS Overpack Boxes

If you get the chemical biological protective system (CBPS) basic issue items (BI1) back from Reset, don't throw away the overpack boxes they come in. The boxes are expensive and are needed by Pine Bluff Arsenal to send out more CBPS BI1. Instructions on sending the box back to Pine Bluff are stamped on its outside. If you have questions about the overpack boxes, email:

[@us.army.mil](mailto:us.army.mil)

or call DSN 793-1506, (309) 782-1506, or email:

[@us.army.mil](mailto:us.army.mil)

## M1064A3 Ramp Actuator Fitting NSN

Get a new pipe nipple for the ramp actuator on your M1064A3 mortar carrier using NSN 4730-01-569-8035 (PN A733XS-25CFB, CAGE 81346). NSN 4730-01-070-0582, which is shown as Item 6 in Fig 329 of TM 9-2350-277-24P (Oct 03, w/Ch 4, Oct 09), is too large.

## FREE BLOWGUN KIT

The first standard automotive tool sets (SATS), NSN 4910-01-490-6453, sent to the field did not include the Blowgun kit used for cleaning air filters. If your SATS has a serial number from KTC-SATS 0001 through KTC-SATS 1119, you can get a free Blowgun kit.

For requisition info, go to the PM-SKOT website: <https://pmskot.army.mil/index.cfm>. Click on [Check your System SKO on Wrty/Rplcmnet web page for Retrofit Availability](#). Then click on [Retrofit](#) and fill out the form.

Questions? Contact TACOM-Rock Island at DSN 793-3385, (309) 782-3385, or email:

[@us.army.mil](mailto:us.army.mil)

## TS-4530 RADAR TEST SET UPGRADE

The TS-4530/UPM radar test set (NSN 6625-01-483-1794, LIN T99847, PN 50-1045-70) for identification friend or foe (IFF) testing will soon require an upgrade for Mode 5 (Enhanced) and Mode 5 Crypto. The upgrade will be performed by the field maintenance calibration support facility (military or civilian) nearest to your location.

To receive the upgrade kit, send DA Form 5106, *Mission Support Plan*, with your POC, location, unit identification codes, nearest repair/calibration facility, and the number of test sets authorized and on-hand to the PD TMDE TEMOD Product Office.

Contact DSN 788-0146, (256) 842-0146, or email:

[@us.army.mil](mailto:us.army.mil)

or DSN 897-2923, (256) 313-2923, or email:

[@us.army.mil](mailto:us.army.mil)

When the TS-4530A/UPM is upgraded, its NSN will change to 6625-01-562-0715 and its part number to 90000125. Its LIN will remain the same.

## M1A1 Hub Cap Replacement

Use NSN 2530-01-552-1192 to order a new hub cap for the hub and arm assembly on your M1A1 tank. NSN 2530-01-063-5862, which is shown as Item 14 in Fig 246 of TM 9-2350-264-24P-1 (Mar 03 w/Ch 6, Jun 09), is a terminal item.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life <sup>right now</sup> on the Condition of Your Equipment?