


BURST BRAKES A REAL BUMMER





Dear Editor,

While performing scheduled services, we've noticed that the M119A2's brake hose, NSN 4720-01-344-6034, is badly rusted about 80 percent of the time. Those rusty hoses can easily burst during brake tests and normal operation.

We recommend that operators keep a close eye on this brake hose and that it also be checked during every service.

The brake hose is easy to reach. Just open the right-hand (curbside) access cover, PN 12591232, on the underside of the trail frame. Then use a flashlight to look at the brake hose inside the frame chamber. If it's rusty, get the brake hose replaced right away.

Wilfried Heitzer
Jochen Rankel
Michael Schwabe
Peter Kohler
Gerhard Scherm
Hans-Juergen Pirner
Maintenance Activity Vilseck, Germany



Editor's note: An excellent suggestion, gentlemen. The procedure for replacing the brake hose is in WP 0045 00 of TM 9-1015-252-34 (Aug 06, w/Ch 1, Feb 08).