


The Pocket Tool



During maintenance tasks, the tool gets whipped out and put to work on all types of screw heads. That's a problem because the tool is not made for all types of screws or every maintenance task.

Using the multi-tool on screw heads and in general maintenance not only can strip out screw heads but can damage other components and hardware.

Stripped screws mean you'll have to use a drill and a punch to remove them. It's better to use the right tool, the right way, so you don't create more work by using the wrong tool, the wrong way, during maintenance.

Don't grab the multi-tool because it's convenient. If the TM calls for a specific tool, use it. That way, you'll avoid damage.

