



COLD WEATHER WEB PAGE

In the battle against the cold, knowledge is your best defense. So, arm yourself with all the facts about cold weather injuries. Visit the U.S. Army Public Health Command (Provisional) website: <http://phc.amedd.army.mil/home/>

From the home page, click on [A-Z Index](#). On the next page, click on [Cold Weather Casualties and Injuries](#). You'll find a variety of documents covering causes, symptoms, first aid and prevention.

SECURE AND STOW WEAPONS CORRECTLY ON COMMERCIAL AIRCRAFT

When deploying, follow Defense Transportation Regulations by removing bolts from weapons and packing them in your checked baggage. A second option is to leave weapon bolts in place, but insert flag safety sticks, NSN 1005-00-418-8557, to lock the bolts.

Bullet OK to Adjust M16/M4 Sight

On Page 19 in PS 693 (Aug 10), we told you not to adjust the M16 rifle/M4 carbine front sight with a bullet or multi-purpose tool. That was partially wrong. It is OK to adjust the sight with a bullet or with the special tool shown in WP 0030-3 in TM 9-1005-319-23&P. But if you adjust the sight with a multi-purpose tool or a nail, you'll eventually ruin the sight.

M1A1 AIM SA TANK SIDECAR SMR CODE

If any sidecar assembly fails on your M1A1 AIM SA (situational awareness) tank, don't toss it in the trash. The SMR code for both the V1 sidecar, NSN 6625-01-497-1915, and the V3 sidecar, NSN 6110-01-577-1839, has recently changed to PAFLL. That means they both can be repaired by a special repair activity and should be turned in for serviceable/unserviceable credit.

M2 Feed Tray Cover Pin

The cotter pin used to secure the M2 machine gun's feed lever to the feed tray cover was accidentally left out of TM 9-1005-213-23&P (Mar 02). Until the cotter pin is added in the next TM change, the belt feed retaining lock pin, NSN 5315-00-013-7137 (PN MS24665-814), or the cotter pin, NSN 5315-00-842-3044 (PN MS244665-283), can be used instead.

M1152A1 HMMWV Fire Extinguisher NSN

The NSN for your M1152A1 HMMWV's fire extinguisher, shown as Item 11 in Fig 266N of TM 9-2320-387-24P (Mar 02, w/ Ch 4, Mar 08), is wrong! Order the right one using NSN 4210-01-562-0852—not NSN 4210-01-525-6692. The part number listed in the TM is correct.

M984A4 HEMTT ELECTRICAL CONTROL BOX

TM 9-2320-326-14&P (EM 0288) gives the wrong NSN for your M984A4 HEMTT's electrical control box. Item 4 of Fig 57 should show NSN 5975-01-558-4419 with part number 3642776. This correction should appear in the next HEMTT -A4 IETM update.

DLA Renames Field Activities

The Defense Logistics Agency (DLA) has renamed its field activities to show clear affiliation with DLA.

Here are some examples:

Old name	New name
Defense Supply Center Columbus	DLA Land and Maritime
Defense Supply Center Philadelphia	DLA Troop Support
Defense Supply Center Richmond	DLA Aviation
Defense Energy Support Center	DLA Energy
Defense Reutilization and Marketing Service	DLA Disposition Services
Defense Distribution Center	DLA Distribution
Defense Logistics Information Service	DLA Logistics Information Service
Document Automation and Product Service	DLA Document Services
Defense Automatic Addressing System Center	DLA Transaction Services
Defense National Stockpile Center	DLA Strategic Materials

For more information, and to see the complete list of name changes, visit: <http://www.dla.mil/wearedla.aspx> Or email: WeAreDLA@dlamail.mil

M915A2/M916A1 Tachometer Kit NSN Change

Use NSN 6680-01-540-3074 to get the tachometer kit for your M915A2 and M916A1 tractor trucks. It replaces NSN 6680-01-502-6523, a terminal item, shown as Item 1 in Fig 335 of TM 9-2320-363-24P.

"MUST SEE" GRS TRAINING VIDEO

Need help with the proper wear of your vehicle's gunner's restraint system? Then take a few minutes to eyeball TACOM's gunner's restraint system informational video online: <https://atn.army.mil>

This video is **mandatory** for operators and supervisors. Just log in with your CAC, click on [Videos](#) on the top menu, click on [Training Skills Videos](#) on the left, then select [The Gunner's Restraint System](#) from the drop-down menu.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?