


# Keeping Records Right While Resetting and Reintegrating



Dear Editor,

I take in SINGGARS systems for theater-provided equipment (TPE) Reset and reintegration. Commanders need to know that when they turn in SINGGARS TPE, that equipment is no longer theirs. It will be reissued to other units. PBOs must drop that equipment off their unit's property books.

Make sure the correct serial numbers are used.

Commanders also need to understand that their unit's organic equipment-not theater provided—should not be turned in to TPE RESET.

Finally, we are finding SINGGARS equipment with the wrong data plates. We have found wrong data plates on all models, but it is especially a problem with the older, wide-body models.

If you think you have a SINGGARS piece of equipment with the wrong serial number or labeled incorrectly, contact your CECOM IT Radio LAR. The LAR will help you identify your system and make sure you're following the correct Reset procedures.

Randy L. Cline  
CEER-T-TPE  
Ft Hood, TX

**Editor's note:** Equipment from overseas is streaming back. All of it will need to be Reset and much of it will be reissued or stored. Keeping good accountability will be hard, but it's a must. It is also everyone's responsibility. We cannot afford a "pass it off and forget about it" mentality. Don't make it the next Soldier's problem. Commanders and top NCOs, make sure all your property is accounted for and that it is listed under the right serial numbers.