

Connie's POST SCRIPTS

PS

HERE'S TO
GO MORE!



M1A2 SEP TARP FOR CROWS

Tankers, once the CROWS (common remotely-operated weapon station) has been added to your M1A2 SEP tank, one tarp just isn't big enough to cover the tank anymore. A second tarp is being added to the BII (WP 0555) in a future update to TM 9-2350-388-10-3. But until then, you'll need to order a second tarp yourself. Get the tarp with NSN 8340-00-841-6456 (olive drab) or NSN 2540-01-330-8062 (tan).

M-ATV WINDOW SEALANT

The Sikaflex® 221 adhesive sealant needed to install the windows on MRAP M-ATVs comes with NSN 8040-01-566-0125. Make a note until this NSN is added to the vehicle's technical manuals.

HGU-56P Chin Strap

The aircrew integrated helmet system's (AIHS) quick-release retention assembly can be ordered with NSN 8415-01-558-1082. But, if you just need the chin strap, use NSN 8415-01-558-3127. The chin pad comes with NSN 8475-01-434-0707.

CECOM CA Reject Notes Online Only

If you turn in a requisition to CECOM and get a CA reject, you will need to go online to view the CA note. The CA note tells you what further action is needed. CECOM no longer sends out CA reject notes by mail. Go to:

<https://lrc3.apg.army.mil/canotes/>

The notes can be accessed by NIIN or document number. Use your AKO user name and password to log in.

M917A1 Dump Truck Switch

Need a thermostatic switch for the transmission control heater on your M917A1 dump truck? Order a new switch with NSN 5930-01-096-7814. This NSN replaces the parts info shown as Item 17 in Fig 298 of TM 9-2320-273-24P (Feb 90).

AEPS Retiring, Applications Moving

The Army Electronic Product Support (AEPS) system will retire on June 30, 2011. Find information about terminated or redirected AEPS applications here:

<https://www.ilsc.army.mil/TULSA/>

The main replacement for AEPS is the TACOM-Unique Logistics Support Applications (TULSA). As each application migrates from AEPS to TULSA or to other websites, links will be updated. You will need your CAC to access TULSA:

<https://tulsa.tacom.army.mil>

For more information, contact Ray Rivero at DSN 786-1985, (586) 282-1985 or email:

ray.rivero@us.army.mil

RG31 MRAP Transmission Fluid

Use only TES-295 transmission fluid in the RG31 MRAP FOVs. Here's what is available:

NSN 9150-01-	Quantity
552-9119	1 qt
565-0981	Six 1-gal containers
552-9157	5-gal container
551-2796	55-gal drum

Do not mix other types of fluids, like Dextron III or IV, in the RG31's transmission. That causes unnecessary wear-and-tear and performance problems.

M969A2 Fuel Tanker Engine

Need a new pump engine for your M969A2 fuel tanker? NSN 2815-01-471-4411 brings the 12-volt Lombardini engine that you have to install. The installation kit comes with NSN 2815-01-459-0006. Make a note until the NSNs are added to your TM.

HMMWV Front Clearance Indicator Light

Item 1 in Fig 61 of TM 9-2320-387-24P lists NSN 6220-01-418-4044 for the front clearance indicator light on your up-armored HMMWV, but that's wrong. Use NSN 6220-01-418-4404 to get the right light.

Up-Armored HMMWV Springs

Get a front spring for the M1114, M1151A1, M1152A1, M1165A1 and M1167 HMMWVs by ordering NSN 5360-01-457-8029. Use NSN 5360-01-524-6029 to get a rear spring for the M1151/A1, M1152/A1, M1165/A1 and M1167 HMMWVs. NSN 5360-01-457-8018 brings a rear spring for the M1114. Make a note until these NSNs are added to TM 9-2320-387-24P.

TROUBLE ACCESSING TECH PUBS?

There is an interface problem between Adobe Reader X® and Internet Explorer 7® (IE 7®) that disrupts the opening of large PDF files for PS Magazine and other technical manuals/bulletins. Because Adobe Reader X® is part of the Army Gold Master it's not possible to remove it and reload Adobe Reader 9®.

LOGSA has contacted Adobe® and they are looking into the problem.

There are two working solutions. First, use the Firefox® Internet browser to access the PDFs. Second, when using IE 7®, instead of trying to "OPEN" the PDF, "SAVE" it to your computer instead. That seems to get the file with little delay. It does, however, strip out the internal links. But, you'll have the publication to use.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on
the Condition of Your Equipment?