


# WHAT'S THE SUPPORT SITUATION?



Dear Half-Mast,

We have a tough time getting parts for the M989 HEMAT trailers in our unit. I hear there's a support solution in place. What's the story on this?

SGT D.A.

Dear Sergeant D.A.,

You heard right. The Army has authorized a swap-out of all basic M989 HEMAT trailers, NSN 2330-01-109-4258, for M989A1 HEMATs, NSN 2330-01-275-7474.

Just give your vehicle's serial or registration number to Marleen Fiantaco at TACOM LCMC. She'll give you disposition instructions for the basic M989. The quickest way to get the replacement trailer, NSN 2330-01-275-7474, LIN T45465, is to submit a DA Form 5106, Mission Support Plan (MSP), through your chain of command.

Contact Marleen at DSN 786-9362, 586-282-9362. Or email: [marleen.fiantaco@us.army.mil](mailto:marleen.fiantaco@us.army.mil)

*Half-Mast*



MAKE XXX COMPANY	XXXXXXXXXXXXXXXXX	MILWAUKEE, WI 53207
MODEL	M989	
MANUFACTURERS SERIAL NO	IS9U51723DMO63043	
REGISTRATION NUMBER	PK04T3	
NSN	XXXXXXXXXXXX	
VEHICLE CURB WEIGHT	6950	LBS
PAYLOAD MAX	XXXXXX	LBS
GROSS WEIGHT RATING MAX	28,950	LBS
DATE OF DELIVERY	2/83	
WARRANTY	12 MONTHS	
CONTRACT NUMBER	XXXXXX	XX XXXXX

Locate M989 trailer serial or registration number