


M4/M4A1
Carbine...

THIS IS ONE OF
THE NEW ENHANCED
BUTTSTOCKS.
WHY IS IT SO HARD
TO INSTALL ON
MY M4?

I'VE HEARD THAT
SOME OF THESE
ARE DEFECTIVE,
AND THIS ONE
DEFINITELY LOOKS
LIKE IT!



DEFECTIVE ENHANCED SLIDING BUTTSTOCKS

Some of the new enhanced sliding buttstocks, NSN 1005-01-544-9825, for the M4/M4A1 carbines are defective.

It's easy to spot the bad buttstocks. They are difficult to install on the M4 or fail to move smoothly or lock in place when installed. (**Note: These are not the standard M4 buttstocks.**)

If your enhanced sliding buttstock doesn't exhibit these problems, you're good to go. But if you've got a bad buttstock, submit a product quality deficiency report (PQDR). Use the link below.

Your unit will receive credit for the defective buttstock.

TO SUBMIT A
PQDR, GO TO:
[http://www.
nslcptsmh.csd.
dlsa.mil/](http://www.nslcptsmh.csd.dlsa.mil/)



- Select Web PQDR under "Web Based Applications" at the upper left-hand side of the page.
- Select EZPQDR under "Important Links."
- Select the EZPQDR link under the Army EZPQDR paragraph.
- Select Accept on the "DOD Warning and Consent Banner" page.
- Fill in all mandatory fields ("m" indicates a mandatory field). Be sure to include the document number, contract number and cage code 58VQ8. This information is critical for accurate processing of the PQDR.
- Select ARMY (TACOM ROCK Island)-W91A52 under "2. Screening Point" on the EZPQDR

Questions? Contact TACOM's Tausha Knowlin at DSN 786-1278, (586) 282-1278, or email: tausha.knowlin@us.army.mil