


CBRN...

SORRY,
BUDDY.

YOUR
TIME HAS
PASSED.

I'M
TAKING
OVER
FOR YOU!

Turn in Riot Control Disperser



The M33/M33A1 riot control disperser (NSNs 1040-00-450-6559 and 1040-00-148-9824; LIN G22348) is obsolete and should be turned in.

It has been replaced by the M37 riot control disperser, NSN 1040-01-463-0157, LIN D20400. The M37 doesn't need the M254 service kit like the M33 did. It comes with a refill/repair kit and its replacement part NSNs are listed in TM 3-1040-287-13&P.

For instructions on turning in the M33/M33A1, contact TACOM's Derek Meredith at DSN 786-1699, (586) 282-1699, or email: derek.b.meredith.civ@mail.mil


M26 Decon...

Decalcify with CLR®

SAYS HERE I'M
SUPPOSED TO USE CLR
TO DECALCIFY YOU,
BUT THERE'S NO NSN
FOR THE CLR LISTED...

...SO
WE'RE KINDA
UP A CREEK!

WE BETTER
TURN TO *PS!*



The M26 decon's TM 3-4230-238-23&P says to use CLR to decalcify if the M26's water pressure is low or the M26 has operated more than 300 hours.

Unfortunately, the CLR NSN was left out of the TM. Get a 5-gal jug of CLR with NSN 6850-01-560-6131.

CLR should be mixed with a CLR/water ratio of 1:8. Follow the instructions in WP 0044 to decalcify.

If you have questions, contact TACOM's Derek Meredith at DSN 786-1699, (586) 282-1699, or email:

derek.b.meredith.civ@mail.mil