

SEE/HMMH...

SHUTDOWN REMINDER

OPERATORS, THE SEE (SMALL EMBLEMMENT EXCAVATOR) AND THE HMMH (HIGH MOBILITY MATERIAL HANDLER) GENERATORS WILL EACH DO A "DEEP SIX" IF YOU DON'T FOLLOW EXACTLY WHAT IT SAYS ON PAGE 2-85 OF TM 5-2420-224-10.


THAT CAN COST YOUR UNIT ABOUT \$300 BUCKS—THE COST OF A NEW GENERATOR.

SO HERE'S THE RIGHT WAY—IT'S SIMPLE...




1

Park the excavator and let the engine idle for 5 minutes.




2

Move the throttle lever to OFF.




3

Turn off the ignition switch.



4

Turn the master disconnect switch key to OFF.



Never turn off the master disconnect switch key or the ignition switch before setting the throttle to OFF.

If you don't shut off the fuel first, the generator will build up a load beyond its capacity and burn out.