

# Wrong NSNs for Takedown Pins



Dear Half-Mast,

We are having trouble getting the M249 machine gun's grooved pin (Item 15 in Fig C-9 of TM 9-1005-201-23&P (Jun 02)). The listed pin's NSN, 5315-01-128-5601, is discontinued, and the replacement NSN, 5315-01-561-6066, brings the wrong pin. We need help.

CW2 M.B.

Dear Chief M.B.,

That's why we're here. The correct NSN for the lower takedown pin (Item 15) is NSN 5315-01-561-4004. But that's not all. The upper takedown pin (Item 16), also has the wrong NSN. Use NSN 5315-01-561-6066 to order it.

Eventually the TM will be corrected, but write in the correct NSNs in the meantime.

*Half-Mast*

## Correct NSNs for takedown pins:

