


MWO Changes NSN

EVER SINCE I GOT MODIFIED, I DON'T KNOW WHAT MY NSN IS ANYMORE!

WELL, YOU'RE IN LUCK. THIS ARTICLE IN PS WILL SET YOU STRAIGHT!



Dear Editor,

I review Army Materiel Status System (AMSS) information as I travel around to units with the MIARNG. A common problem I find is that units have the wrong NSN listed for their MK 19s.

When the MK 19 had MWO 9-1010-230-50-1 applied, its NSN was changed from 1010-01-126-9063 to 1010-01-490-9697, its model from MK 19 to MK 19 MOD3, and its end item code (EIC) from 4AE to 4BL.

But when you look up the MK 19's line item number (LIN) of M92362 on the Maintenance Master Data File (MMDF), it has the NSNs and EICs reversed. So the wrong NSN and EIC are often entered into SAMS-E.

Armorers need to double check that they have NSN 1010-01-490-9697 and EIC 4BL listed for their MK 19 MOD3s. All MK 19s should have been modified by now.

SGT Phil Michmerhuizen
COMET
Lansing, MI

Editor's note: Good point, Sergeant. Making this correction now, armorers, can save you headaches later.