

**6K VRRT FORKLIFT SOLENOID**

To get the fuel shutoff solenoid for the 6K variable reach rough terrain forklift, use NSN 5945-01-452-9300. Make a note until the NSN is added to TM 10-3930-660-24P.

**EPM Protects HMMWV Batteries**

Leaving the linear amp or the blue force tracker (BFT) antenna power switch turned on drains and kills batteries on your HMMWV. Avoid this trouble by ordering an electric power manager (EPM) kit, NSN 5999-01-576-9653. It works on M997A2, M998A2, M1025A2, M1035A2, M1043A2, M1045A2, M1097A2 and ECV vehicles: M1113, M1114, M1151, M1151A1, M1151A1 w/B1, M1152, M1152A1, M1152A1 w/B2, M1165, M1165A1 and M1165A1 w/B3. We'll tell you when a kit for basic and other -A1 series HMMWVs is available.

**VRLA Battery Pubs Updated**

Two maintenance publications involving VRLA (valve-regulated lead-acid) batteries have been updated.

TM 9-6140-200-13, *Operator and Field Maintenance for Automotive Lead-Acid Storage Batteries*, dated May 2011, covers all types of automotive batteries.

TB 9-6140-252-13, *Recharging Procedures for Automotive Valve Regulated Lead-Acid Batteries*, dated September 2011, is also available.

New VRLA batteries should come with a maintenance sticker that tells you the battery can be charged many times before disposal is authorized. It will also reference the latest pub.

You can view the battery TM and TB online:

<https://www.logsa.army.mil/etms/online.cfm>

**M113A3 FOV, M58 Ramp Hydraulic Hose NSN**

Get a new hydraulic hose for the ramp actuator on your M113A3, M577A3, M1068A3, and M58 vehicles with NSN 4720-00-278-4892 (PN 2565-6, CAGE 01276). NSN 4720-00-006-4006, which is listed as Item 4 in Fig 328 of TM 9-2350-277-24P (Oct 03, w/Ch 4, Oct 09), is a terminal item.

**M109A6 Paladin Traverse and Elevation Selector Valves**

Get a new socket-head screw for your Paladin's traverse and elevation selector valves with NSN 5305-01-185-4493 (PN NAS1352-5-12P, CAGE 80205). NSN 5305-00-983-5346, which is listed as Item 17 in Fig 196 and Item 13 in Fig 197 of TM 9-2350-314-24P-2 (Feb 99, w/Ch 5, Jul 09), is a terminal item.

**MaxxPro MRAP Tank Cap**

The overflow cap for the MaxxPro's radiator (surge) tank is now available separately with NSN 2930-01-588-5040. You'll find the tank shown as Item 2 in Fig 33 of TM 9-2355-106-23P.

**M113-Series FOV Seat Pin**

Get a new spring pin for the driver's and radio operator's seat on your M113-series FOV with NSN 5315-00-814-4456 (PN NAS561C4-24, CAGE 80205). NSN 5315-00-584-9221, which is shown as Item 22 in Fig 243 of TM 9-2350-261-24P (Aug 05) and Item 22 in Fig 266 of TM 9-2350-277-24P (Oct 09), is a terminal item.

**M901A1 Anti-Tank Vehicle Driver's Hatch Yoke Support Assembly**

Get a new socket-head screw for the driver's hatch yoke support assembly on your M901A1 with NSN 5305-00-038-8995 (PN NAS1352-4-16P, CAGE 80205). NSN 5305-00-978-9385, which is shown as Item 23 in Fig 220 and Item 56 in Fig 223 of TM 9-2350-261-24P (Aug 05), is a terminal item.

**CEP for IHADSS Helmet**

Here's the latest word on communications earplugs (CEPs) for your integrated helmet and display sighting system (IHADSS). NSN 5965-01-536-5644 brings you the CEP Kit. Installation instructions can be found at: <http://www.cep-usa.com>

If you have problems getting the instructions, contact David Jirak at (586) 282-1091 or email:

[david.e.jirak.civ@mail.mil](mailto:david.e.jirak.civ@mail.mil)

**IHADSS Helmet Visors**

Here's the latest word on visors. If you still have legacy SPH-4 style visors on hand, they are obsolete and no longer supported. If you need assistance on what to do with old visors, contact David Jirak, (309) 782-7185, or email:

[david.e.jirak.civ@mail.mil](mailto:david.e.jirak.civ@mail.mil)

For the air warrior POC contact Clayton Pitts, (256) 955-8712 or email:

[clay.pitts1@us.army.mil](mailto:clay.pitts1@us.army.mil)

**M915A4 Engine RPM Correction**

There are several references in TMs 9-2320-303-10, -24-1 and -24-2 where the Max (no-load) engine rpms are shown as 2,100. This is wrong. It should read 2,400.

**Up-Armored HMMWV Brake Caliper Adapters**

The brake caliper adapters listed as Item 4 in Fig 125A and Item 14 in Fig 125B in TM 9-2320-387-24P (Mar 02, w/C5 Aug 09) are wrong. The front and rear adapter NSNs are reversed. Get the left front adapter with NSN 2530-01-567-0607, and the right front with NSN 2530-01-567-0587. The left rear adapter comes with NSN 2530-01-567-0232, and the right rear with NSN 2530-01-567-0400. Make a note until the TM is updated.

**HOT STUFF: PS INDEX HOOKS YOU UP**

A hotlinked index of PS articles from 2000-2011 is now at your fingertips. You can even save a copy of the index to your computer's hard drive. When you find a PS article that you want to read, just click on its link in the index and the article will open in your web browser. Visit:

[https://www.logsa.army.mil/pub/psissuesA/PS\\_index2000-2011.pdf](https://www.logsa.army.mil/pub/psissuesA/PS_index2000-2011.pdf)

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life <sup>right now</sup> on the Condition of Your Equipment?