

Connie's POST SCRIPTS

FMTV Troop Limits Decal

Need to know how many troops can safely fit into your FMTV truck's cab or cargo bed? Eyeball the troop capacity table in the operator's manuals. There's also a troop capacity decal, NSN 7690-01-559-9001, being installed in the cab on the power distribution cover. If your truck doesn't have one, order it. And note these limits:

Model	Cab	Cargo bed
M1078/M1081/ M1090/M1094	3 troops	12 troops
M1083/M1084/M1093	3 troops	14 troops
M1085/M1086	3 troops	20 troops
All others	3 troops	No troops

ACH TM NUMBER CORRECTION

On Page 58 in PS 713 (Apr 12), the TM number we gave for the *Operator's Manual for Advanced Combat Helmet* (May 10) was wrong. It should be TM 10-8470-204-10.

AMCOM 2028 CHECKUP

If you've submitted an unclassified DA Form 2028, *Recommended Changes to Equipment Technical Publications*, and want to check the latest status, go to: <https://pubsweb.redstone.army.mil/> Then click on the link AMCOM 2028's Online (Online Request). While there, you can also submit a new unclassified 2028, view web 2028 attachments and email the AMCOM 2028 point of contact.

AFES Informational Video Now Available

All automatic fire extinguisher systems (AFES) serve the same purpose: to quickly put out fires in tactical and combat vehicles and to protect the vehicle's driver and passengers. To help with this, TACOM LCMC has released an informational video on the AFES. The video discusses common components across many platforms. It also tells you how to properly operate the AFES. To get a free copy for your unit, call DSN 786-4276, (586) 282-4276, or email:

tacom-lcmc.ilsc_utap@mail.mil

Make sure you give them a good military shipping address.

M1112 Axle Spindle Nut

To get a spindle nut for the axle on your M1112 400-gal water trailer, use NSN 5310-01-226-8735. This NSN replaces the one shown as Item 28 in Fig 13 of TM 9-2330-397-14&P.

CATERPILLAR DIAGNOSTIC WEBSITE

To get the diagnostic procedures for electronic engines and transmissions on Caterpillar construction equipment, visit this URL:

<https://akoapps.amrdec.army.mil/tacom>

By the way, you'll need your CAC card to access this website.

ATLAS II Forklift Special Seal Tool

The wrong rear seal installation tool was added to 200 ATLAS II special tool kits. The correct tool is NSN 5120-01-334-7012. You can get a replacement tool from JLG Industries by contacting Terri Bradley toll free at (866) 554-7782 (Press 1 for parts), (717) 485-5161, ext. 3719, or by email at:

tibradley@jlg.com

The tool is free to units through 13 Sep 12. After that, you'll have to order it through the supply system or direct from JLG.

New Website for Cancelled CECOM (B16) Requisitions

Requisition cancellation notices at CECOM (B16) are now automated, and there is a new website that can tell you why your B16 requisition was cancelled. You'll need your Common Access Card (CAC) to access it. Go to: <https://lrcweb1.apg.army.mil/i2log/misc/ca.cfm>

You can search for your requisition by document number, DODAAC or NIIN. Questions? Contact Diane Johnson at DSN 848-6322, (443) 861-6322, or email: diane.johnson1.civ@mail.mil

A New Slice of CECOM's PIE

The Logistic Readiness Center's (LRC) Policy and Information Encyclopedia (PIE) lets you search for CECOM equipment by type, NSN/NIIN, LIN, part number/drawing number, TM number, item name or office symbol. The database recently moved. The new URL is:

<https://lrcweb1.apg.army.mil/pie/index.cfm>

For more information about LRC's PIE, contact Jeff Potter at DSN 848-6458, (443) 861-6458, or email:

jeffery.i.potter6.civ@mail.mil

M1114, M1151A1 HMMWV OGPK GLASS

Need to replace the objective gunner protection kit's (OGPK) weapon shield and side glass on your M1114 and M1151A1 HMMWVs? Use the following NSNs:

Left side weapon shield glass -

NSN 6650-01-550-7555

Right side weapon shield glass -

NSN 6650-01-550-7525

Side glass (bucket) -

NSN 6650-01-550-7534

New URL for PM J-AIT

The Product Manager Joint-Automatic Identification Technology (PM J-AIT) website is now at:

<http://www.ait.army.mil>

Check it out for support on AIT, Radio Frequency In-Transit Visibility (RF-ITV) and Radio Frequency Identification (RFID) hardware, software, technical engineering and maintenance.

M500 TM Correct on Extractors

On Page 37 of PS 711 (Feb 12), we said that the M500 shotgun's TM 9-1005-338-13&P had the cartridge extractors reversed in WP 0029 00-1. That was wrong. The extractors are not reversed and the TM is correct.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?