


Up-Armored
HMMWV...

FIX CARGO SHELL LATCH PLATE FAILURE



If your M1151, M1151A1, M1151A1WB1, and M1167 HMMWVs have failing cargo shell forward latch plate assemblies, you might be a little frustrated. Here's what you can do to prevent the failures and ease the frustration.

If your HMMWV's hatch doesn't close smoothly during PMCS, tell your mechanic. And make sure you're opening and closing it the right way.

Also, ensure the forward latches are fully engaged with the forward strikers before opening the cargo door from the rear position. That should help protect the cargo shell forward latch plate assembly.

But if you do all that and there's still a problem, your HMMWV's cargo shell forward latch plate assembly may have failed.

You can't find replacement procedures in the TM yet, but you can get them from TACOM LCMC. Just send your unit information and request to:

TACOM LCMC

Program Manager, Light Tactical Vehicles (PM-LTV)

ATTN: SFAE-CSS-TV-L

Warren, MI 48397-5000

Questions? Contact Oscar Chapman at DSN 786-6510, (586)282-6510, or

oscar.b.chapman.civ@mail.mil

and Nathaniel Zachary at DSN 786-4305, (586)282-4305, or

nathaniel.j.zachary.civ@mail.mil