


Use Correct LINs and EICs



During the rapid fielding initiative (RFI), several laser target locators were fielded using non-standard line item numbers (NSLNs), such as Z00692. Some of these systems may have been picked up as a substitute for the AN/PVS-6 (LIN M74849).

Property book officers should immediately change these NSLNs to the correct LINs to ensure asset visibility and property accountability. In addition, end item codes (EICs) have been assigned to all laser range finders and laser target locators. These should be added to the property book.

Here are the correct LINs and EICs:

LIN	Model	NSN	Common name	Official nomenclature	End item code
T27471	AN/PED-3	1240-01-538-4212	Mark VII LTLS	Target locator module	4XD
T27471	AN/PED-3A	1240-01-562-8083	Vector21 LTLS	Target locator module	4XE
L05003	AN/PED-4	1240-01-562-8084	Mark VIII LTLM	Target locator module	4XB
L05003	AN/PED-5	1240-01-590-4552	TRIGR LTLM	Target locator module	4XC
J68653	AN/PSQ-23	5855-01-535-1905	STORM (black)	Integrated small arms illuminator	4XF
J68653	AN/PSQ-23	5855-01-577-5946	STORM (tan)	Integrated small arms illuminator	4XG

If you have unserviceable laser range finders or laser target locators, turn them in so they can be fixed and returned to the field. Your property book officer should report them to National Inventory Control Point (NICP) B14 using an FTE (report of excess) and follow the instructions in Chap 7 of AR 725-50 (Nov 95), *Requisition and Issue of Supplies and Equipment*. The NICP will provide disposition instructions through an FTR (reply to report of excess) with exception data that includes detailed disposition and shipping instructions. All items **must** be turned in complete.

If you have questions about laser target locators, contact Mauricio Martinez at DSN 312-654-3320, (703) 704-3320, or email:

mauricio.d.martinez.civ@mail.mil

Direct laser range finder questions to Scott Vance at DSN 312-654-4808, (703) 704-4808, or email:

louis.s.vance.ctr@mail.mil

Questions about turn-in or maintenance of laser range finders or target locators go to Jeffrey York at DSN 312-786-1344, (586) 282-1344, or email:

jeffrey.l.york2.civ@mail.mil

M249
Machine
Gun...

MWO MISSED

IF YOUR M249 HAS BEEN MWO'D... ...IT SHOULD LOOK LIKE THIS!



Dear Editor,

As a member of the COMET team at Joint Base Lewis-McChord (JBLM), I see numerous M249 machine guns that have not had MWO 9-1005-201-30-6 applied.

The MWO, which added a new rail system and pistol grip, should have been applied by June, 2010. Armorers need to check all their M249s for the new flat-top rail system, which makes it easier to mount optics.

The MWO can be found on the ETM site:

<https://www.logsa.army.mil/etms/index.cfm>

Your direct support performs the MWO.

Doug Stewart
COMET
JBLM, WA

Editor's note: Thanks for the heads-up, Doug. Armorers, don't let your M249s get out of date. If you have any questions, contact your local TACOM logistics assistance representative (LAR).