



NEED A COMPASS?

Make a note, aviators, that the only authorized lensatic compass to be in the air warrior primary survival gear carrier (PSGC) is NSN 6605-01-196-6971.

LIW Portal FAQs

The Logistics Support Activity (LOGSA) has posted frequently asked questions (FAQs) about finding info in the redesigned Logistics Information Warehouse (LIW) at:

https://liw.logsa.army.mil/resources/documents/liw_portal_help_faq.pdf

If you need LIW assistance, contact LOGSA's help desk Toll Free at 1-866-211-3367, CONUS DSN 645-7716, OCONUS DSN 312-645-7716, commercial 256-955-7716 or email:

usarmy.redstone.logsa.mbx.help-desk@mail.mil

HYEX Track Assembly NSN

Get a new 51-link track roller assembly for your hydraulic excavator, Type 1, with NSN 2540-01-583-9967. It fits HYEX models 230LCR, 230LCRD, 240DLC and 250GLC. The new assembly replaces NSNs 2530-01-476-0523 and 2530-01-476-0518, which are shown as Item 1 in Fig 8 of TM 5-3805-280-23P-1 (Jul 11).

Comics Worth Keeping

Are you a fan of comics, especially PS? Check out Virginia Commonwealth University's archived collection of early copies of *PS Magazine*. The digital collection features the art of famous comic book artist Will Eisner, and covers the *PS* publication years from 1951-1971 (issues #1-229). It's free to browse:

<http://go.vcu.edu/psmagazine/>

FRS Outrigger Pad

Get a new outrigger pad for the crane assembly on your forward repair system (FRS) with NSN 4940-01-533-1621. It replaces NSN 2590-01-461-1648, which is shown as Item 1 in Fig 222 of TM 9-4940-568-24P (Jan 08, w/Ch 1, Jul 11). A missing outrigger pad makes the crane assembly NMC.

HEMTT A4 REAR HUB AND DRUM ASSEMBLY BOLT

The part number for the right-hand bolt on your HEMTT A4's rear hub and drum assembly isn't listed correctly in the IETM. So Item 3 of Fig 199 in TM 9-2320-326-14&P (EM 0288, Oct 08) will be updated to include part number W1133-R and NSN 5307-01-212-4401. The left-hand bolt, part number W1133-L and NSN 5307-01-212-4400, is already correct.

APPROVED COMPASS FOR PSGC

When dealing with what goes into the air warrior ensemble, not just any compass will do for the primary survival gear carrier (PSGC). The lensatic compass, NSN 6605-01-196-6971, is what ALSE techs are authorized to place in their gear. Table 1 in IETM, EM 0250, TM 1-1680-377-13&P, WP 0100 00 tells you where the compass goes and that it's mandatory, not optional.

Updated Email Address for PBUSE Help

Due to the Enterprise email migration, the PBUSE help desk has a new email address for customer support. Email them at: usarmy.lee.sec.mbx.leeec-seclee-cso@mail.mil
The PBUSE help desk phone numbers have not changed. Call 1-(866)-547-1349, DSN 687-1051, OCONUS (312) 687-1051 or submit a help desk request to: <https://s4if.lee.army.mil>

HEMTT A4 POWER TRANSFORMER NSN CHANGES

The power transformer for your HEMTT A4, shown as Item 2 in Fig 126 in TM 9-2320-326-14&P, has been changed from NSN 5950-00-015-9520 to NSN 6130-01-558-4871. Note this change until the TM is updated.

M1117 ASV ALTERNATOR BELT

Get the alternator belt for your M1117 armored security vehicle (ASV) with NSN 3030-01-364-3395. NSN 3030-01-563-8929, which is shown as Item 51 in Fig 47 of TM 9-2320-307-24P (Sep 10), is too short.

M149A2 WATER TRAILER FAUCET

Get the single faucet for your M149A2 400-gal water trailer with NSN 4510-01-433-0396. That replaces NSN 4510-00-595-1785, which is shown as Item 1 in Fig 28 of TM 9-2330-267-14&P (Jul 91).

HMEE-1 Training Material

Operator training material for the High Mobility Engineer Excavator is now available in the Library of TACOM Training Information Site (LOTTIS):

<https://customerreports.tacom.army.mil/pls/htmldb/f?p=150>

If you cannot find the training material you need, write to:

dami_utap@conus.army.mil

RTCH O-RING KIT NSN

NSN 5330-01-529-0690 gets a new O-ring kit for the hydraulic fittings on the rough terrain container handler (RTCH). Make a note of this NSN until it's added to TM 10-3930-675-24P.

DO YOU NEED BANDAGES?

Aircraft kits and vests always need bandages. You can order a box of 300 with NSN 6510-00-913-7909. Make a note that FED LOG shows a shelf life code of 7. That means the bandages expire after 36 months.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?