




CONTROL UNIT DAMAGE SPARKS MOD KIT!



Word from the field is there's been a sharp increase in damaged roller control units (RCUs) for the self-protected adaptive roller kit (SPARK II) that mounts to the front of your MRAP M-ATV.

Seems the touch screen on these RCUs is easily damaged by careless boots, Kevlar, rifle stocks or just simple neglect. Just one busted RCU costs about \$3,500 to replace. In the meantime, the vehicle's ability to explode improvised explosive devices is out of service. Plain and simple, the SPARK II is NMC!



The headshed has a modification kit in the works to protect the RCU's touch screen. It includes a more durable case that protects the screen.

Until the kit becomes available, remember to keep anything harder than your finger away from the RCU's touch screen.