

Connie's POST SCRIPTS

SAY, BULL,
REMEMBER OUR POST
SCRIPTS SECTION?



SURE DO,
CONNIE!



FMTV -10 TM Binder

Get a binder for your FMTV's -10 TM with NSN 7510-00-889-3494. This green binder measures 2 1/2 x 8 x 10 inches.

966H Scoop Loader Axle Oil

The axle oil, NSN 9150-00-491-7197, listed as Item 31 in WP 0233 00-4 of TM 5-3805-291-23-2, is for arctic conditions only. Using it for anything other than arctic conditions will result in axle failure.

HGU-56/P Helmet Update

The HGU-56/P aircrew integrated helmet system (AIHS) has a new quick-release chin strap assembly, NSN 8415-01-558-1082. The assembly is made up of the chin strap, NSN 8415-01-558-3127, and the quick-release pad, NSN 8475-01-434-0707. These NSNs replace the old chin strap assembly, NSN 8415-01-394-8023, which is a terminal item.

M16/M4 MAGAZINE TOOL

Armorsmen need to make sure they have the tool for weeding out bad M16 rifle/M4 carbine magazines. The tool, NSN 5120-01-574-0036, costs less than \$25. For instructions on using the tool, see Page 21 of PS 700 (Mar 11):

<https://www.logsa.army.mil/psmag/archives/PS2011/700/700-21.pdf>

M1 Tank FBCB2 Correction

The FBCB2 central processing unit (CPU) article on Page 5 of PS 720 (Nov 12) was mistakenly listed as applying to the M1A2 SEP tank. The information actually applies only to the M1A1SA tank. The M1A2 SEP tank's FBCB2 is completely embedded.

AR 11-1 Revision Makes Rounds

A major revision to AR 11-1, *Command Logistics Review Program*, went into effect 27 November 2012. It covers policies and responsibilities for managing the Command Logistics Review Program (CLRP). There is an added requirement for mandatory annual reports to the Deputy Chief of Staff G-4. Download the revised AR at:

http://www.apd.army.mil/pdf/files/r11_1.pdf

The FREE Ensemble TM is on the Net

Now that the fire resistant environmental ensemble (FREE) is being fielded, you'll need to keep it in good shape. Download TM 10-8415-237-10 from the LOGSA ETM and Air Warrior websites:

<https://www.logsa.army.mil/etmpdf/files/080000/086849.pdf>

<https://airwarrior.redstone.army.mil/Library/DocumentTracking.aspx?filterType=All>

HEMTT A4 Forward Lighting Kit Brightens Wide Area

Need lighting for a wide area that works on your unit's HEMTT A4 trucks? Get the forward lighting system with NSN 6220-01-584-9947. That brings the kit and installation instructions for a front light bar with six lights. It costs about \$6,800.

M978A4 HEMTT Hardware Update

There are a couple of NSN changes for your M978A4 HEMTT's hardware shown in Fig 438 of TM 9-2320-326-14&P. The coupling clamp, NSN 4730-00-142-1589, shown as Item 6, now comes with NSN 4730-01-514-5018. And the gasket, NSN 5330-01-161-6104, shown as Item 8, now comes with NSN 5330-00-391-8491. Make a note until the TM is updated.

Online Archive of The HIP Times Now Available

Back issues of *The Heavy Tactical Vehicle Improvement Program (HIP) Times* are now available online. Eyeball the TACOM-produced newsletter's HEMTT, PLS, HET and M915 truck maintenance updates from 1994 to the present at:

<http://www.themotorpool.org>

Use a military email address to gain access.

BATTERY BOX COATING COMPOUND

Any time the batteries are removed from your vehicle, eyeball the condition of the battery box. Use a wire brush to scrape off rust and old paint. After cleaning up the debris, protect the bare metal inside the box with bituminous coating compound. NSN 8030-00-290-5141 brings a gallon of the compound.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on
the Condition of Your Equipment?